
*In The Name of God The Most
Compassionate, The Most Merciful*



Electric Machines II





Table of Contents

1. Single-Phase Transformers

2. Principle of Alternating Current (AC) Machines

3. Three-Phase Induction (Asynchronous) Machines



Chapter 2

Principle of AC Machines

2.1. Rotating Magnetic Field

2.2. Electrical and Mechanical Angles

2.3. Induced Voltage

2.4. Pole-pitch and Coil-pitch

2.5. Pitch Factor

2.6. Distribution Factor

2.7. Winding Factor



Rotating Magnetic Field

Consider the following **3-phase AC** machine with **2 poles** and **concentrated winding**. The 3-phase AC currents can be expressed as:

$$i_a(t) = I_m \cos \omega t$$

$$i_b(t) = I_m \cos(\omega t - 120^\circ)$$

$$i_c(t) = I_m \cos(\omega t + 120^\circ)$$





Rotating Magnetic Field

The rotating magnetomotive force (MMF) can be expressed as

$$\vec{F}(\theta, t) = \vec{F}_a(\theta, t) + \vec{F}_b(\theta, t) + \vec{F}_c(\theta, t)$$

$$\vec{F}(\theta, t) = Ni_a(t) \cos \theta + Ni_b(t) \cos(\theta - 120^\circ) + Ni_c(t) \cos(\theta + 120^\circ)$$





Rotating Magnetic Field

The rotating magnetomotive force (MMF) can be expressed as

$$\vec{F}(\theta, t) = Ni_a(t) \cos \theta + Ni_b(t) \cos(\theta - 120^\circ) + Ni_c(t) \cos(\theta + 120^\circ)$$

$$\begin{aligned}\vec{F}(\theta, t) &= NI_m \cos \omega t \cos \theta \\ &+ NI_m \cos(\omega t - 120^\circ) \cos(\theta - 120^\circ) \\ &+ NI_m \cos(\omega t + 120^\circ) \cos(\theta + 120^\circ)\end{aligned}$$

$$\vec{F}(\theta, t) = \frac{3}{2} NI_m \cos(\omega t - \theta)$$



$$\cos a \cos b = \frac{1}{2} \cos(a - b) + \frac{1}{2} \cos(a + b)$$

Electrical & Mechanical Angles

Consider an AC machine with p poles.

$$\theta_{elec} = \frac{p}{2} \theta_{mech}$$

$$\omega_{elec} = \frac{p}{2} \omega_{mech}$$



Induced Voltage

Consider an AC machine. Ideally the flux density seen by coil aa' is expressed as

$$B_a(t, \theta) = B_m \cos \theta \cos \omega t$$



The corresponding air-gap flux is

$$\phi(t) = \int_A B \cdot dA \Rightarrow \phi_a(t) = \int_0^L \int_{-\pi/2}^{\pi/2} B_a \cdot r d\theta dl$$

$$\phi_a(t) = 2LrB_m \cos \omega t$$

$$\phi_a(t) = \phi_m \cos \omega t \quad \phi_m = 2LrB_m$$

where L is the stator axial length and r is the stator inner radius



Induced Voltage

$$\phi_a(t) = \phi_m \cos \omega t$$

$$\phi_m = 2LrB_m$$

The induced voltage in coil aa' with N turns is



$$e_a(t) = -N \frac{d\phi_a}{dt}$$

$$\rightarrow e_a(t) = N\phi_m \omega \sin \omega t$$

$$e_b(t) = N\phi_m \omega \sin(\omega t - 120^\circ)$$

$$e_c(t) = N\phi_m \omega \sin(\omega t + 120^\circ)$$

$$E_{rms} = \frac{N\phi_m \omega}{\sqrt{2}}$$



Induced Voltage

$$E_{rms} = \frac{N\phi_m \omega}{\sqrt{2}} \rightarrow E_{rms} = \frac{N\phi_m 2\pi f}{\sqrt{2}}$$



The RMS induced voltage in each phase having N turns in series with **concentrated** and **full pitch** windings is

$$E_{rms} = 4.44N\phi_m f$$

For machines with **distributed** and/or **short pitch** windings the RMS induced voltage is



$$E_{rms} = 4.44N\phi_m f k_p k_d$$

Where k_p is the pitch factor and k_d is the distribution factor.





Pole Pitch

- Pole pitch:** is the angle between two adjacent poles in electrical angle. Pole pitch is always 180 electrical degrees regardless of the number of poles.



Coil Pitch

- Coil pitch**: is the angle between two sides of one armature coil in electrical angle. If the coil pitch is 180 electrical degrees, the coil is a **full-pitch coil**; otherwise it is called **short-** or **chorded-pitch coil**.



Pitch Factor


- Assume the axial length of the stator is l and the coil pitch is ρ as shown in the figure

$$e = (\vec{V} \times \vec{B}) \cdot \vec{l}$$

$$e = VBl \sin(\vec{V}, \vec{B})$$

$$\begin{cases} e_a = VBl \sin\left(\theta + \frac{\pi}{2} - \frac{\rho}{2}\right) \\ e_{a'} = VBl \sin\left(\pi + \frac{\pi}{2} - \frac{\rho}{2} - \theta\right) \end{cases}$$

$$\begin{cases} e_a = VBl \cos\left(\theta - \frac{\rho}{2}\right) \\ e_{a'} = -VBl \cos\left(\theta + \frac{\rho}{2}\right) \end{cases}$$




Pitch Factor

- Assume the axial length of the stator is l and the **coil pitch** is ρ in **electrical angle** as shown in the figure

$$\begin{cases} e_a = VBl \cos\left(\theta - \frac{\rho}{2}\right) \\ e_{a'} = -VBl \cos\left(\theta + \frac{\rho}{2}\right) \end{cases}$$

$$|e_{aa'}| = 2VBl \sin \theta \sin\left(\frac{\rho}{2}\right)$$



Pitch Factor

$$|e_{aa'}|_{Full-pitch} = 2VBl \sin \theta$$


$$|e_{aa'}|_{Short-pitch} = 2VBl \sin \theta \sin\left(\frac{\rho}{2}\right)$$

The pitch factor is defined as

$$k_p = \frac{|e_{aa'}|_{Short-pitch}}{|e_{aa'}|_{Full-pitch}}$$

Therefore the pitch factor is

$$k_p = \sin\left(\frac{\rho}{2}\right)$$




Pitch Factor

- Since the induced voltage may not be ideal sinusoidal, the pitch factor is expressed for all harmonics

$$k_{pn} = \sin\left(\frac{n\rho}{2}\right)$$

- Why is short-pitch coil used?
- Although short-pitch coil decreases the induced voltage (by about 3%), it **decreases** the **disturbing harmonics** significantly (by about 70 to 80%).
- Disturbing harmonics in electric machines are 5 and 7;



Pitch Factor

- Example:** Consider a 3-phase, 2-pole machine having pitch coil ratio of 5/6. Calculate the pitch factor for odd harmonics 1 to 7.

$$\text{Pitch factor ratio} = \frac{\rho}{\pi}$$



$$\rho = \frac{5\pi}{6}$$

Electrical rad


$$k_{pn} = \sin\left(\frac{n\rho}{2}\right)$$

$$k_{p1} = \sin\left(\frac{5\pi}{2 \times 6}\right) = 0.966$$

$$k_{p3} = \sin\left(\frac{3 \times 5\pi}{2 \times 6}\right) = -0.707$$

$$k_{p5} = \sin\left(\frac{5 \times 5\pi}{2 \times 6}\right) = 0.259$$

$$k_{p7} = \sin\left(\frac{7 \times 5\pi}{2 \times 6}\right) = 0.259$$




Distributed Windings

- To make the **MMF more sinusoidal**, distributed windings are used.
- Consider the following 2-pole single-layer distributed winding AC machine:
- The induced voltage in phase a is:

$$\vec{E}_{aa'} = \vec{E}_{aa'1} + \vec{E}_{aa'2} + \vec{E}_{aa'3}$$

$$\vec{E}_{aa'} = E_{rms} \angle -20 + E_{rms} \angle 0 + E_{rms} \angle 20$$

$$\vec{E}_{aa'} = 2.88 E_{rms} \angle 0$$



Distribution Factor


- Distribution factor is defined as:

$$k_d = \frac{\text{Induced voltage for distributed winding}}{\text{Induced voltage for concentrated winding}}$$

- In previous example


$$k_d = \frac{2.88E_{rms}}{3E_{rms}}$$

$$k_d = 0.96$$



Multi-layer Winding

- Most of AC machines, especially large machines, have **2-layer** winding.
- 2-layer winding has the following **advantages** compared to single-layer winding:
 1. Simpler winding
 2. Simpler connection
 3. Higher mechanical strength
 4. Optimal use of slots
 5. Lower cost



Distribution Factor

- Distribution factor is defined as:


$$k_d = \frac{\text{Induced voltage for distributed winding}}{\text{Induced voltage for concentrated winding}}$$

- Assume the angle between two adjacent slots is γ in electrical angle and the number of slots per pole per phase is m , therefore the distribution factor is written as

$$k_d = \frac{\sin \frac{m\gamma}{2}}{m \sin \frac{\gamma}{2}}$$

- In n -th harmonic it is

$$k_{dn} = \frac{\sin \frac{mn\gamma}{2}}{m \sin \frac{n\gamma}{2}}$$



Winding Factor

- Winding factor is defined as


$$k_w = k_p k_d$$

$$k_p = \sin\left(\frac{\rho}{2}\right)$$

$$k_d = \frac{\sin \frac{m\gamma}{2}}{m \sin \frac{\gamma}{2}}$$

$$k_{pn} = \sin\left(\frac{n\rho}{2}\right)$$

$$k_{dn} = \frac{\sin \frac{mn\gamma}{2}}{m \sin \frac{n\gamma}{2}}$$



Winding Factor

- Example:** Consider a 3-phase, **2-pole** generator where its stator winding connected in star form. The machine has 2-layer, short-pitch, distributed winding with 4 coils per phase. If each coil has 10 turns, rotor is rotated with 3000 rpm and the flux of each pole is 0.019 Wb, calculate the phase induced voltage.

$$N_l = 2$$

$$N_{cp} = 4$$

$$N_{tc} = 10$$

$$n_r = 3000 \text{ rpm}$$


$$\phi = 0.019 \text{ Wb}$$

$$p = 2$$

$$E_{aa'} = ?$$

$$E_{rms} = 4.44 N_t f \phi k_w$$

$$k_w = k_p k_d$$



Winding Factor

- Solution:** $N_l = 2$ $N_{cp} = 4$ $N_{tc} = 10$ $n_r = 3000$ rpm

$$\phi = 0.019 \text{ Wb}$$

$$p = 2$$

$$E_{aa'} = ?$$

$$E_{rms} = 4.44 N_t f \phi k_w$$

$$k_w = k_p k_d$$

$$f = \frac{p}{2} \frac{n_r}{60} = 50 \text{ Hz}$$

Number of turns per phase is


$$N_t = N_{tc} N_{cp} = 40$$

Coil pitch is

$$\rho = 150 \text{ elec.deg.}$$

Pitch factor is found as

$$k_p = \sin\left(\frac{\rho}{2}\right) = \sin\left(\frac{150}{2}\right) = 0.966$$



Winding Factor

- Solution:** $N_l = 2$ $N_{cp} = 4$ $N_{tc} = 10$ $n_r = 3000$ rpm

$$\phi = 0.019 \text{ Wb}$$

$$p = 2$$

$$E_{aa'} = ?$$

$$E_{rms} = 4.44 N_t f \phi k_w$$

$$k_w = k_p k_d$$

$$f = 50 \text{ Hz} \quad N_t = 40 \quad k_p = 0.966$$

- Number of slots per pole per phase


$$m = N_s / 3p = 2$$

- Slot-pitch is

$$\gamma = \frac{p}{2} \frac{360}{N_s} = \frac{360}{12} = 30 \text{ elec.deg.}$$

- Distribution factor

$$k_d = \frac{\sin \frac{m\gamma}{2}}{m \sin \frac{\gamma}{2}} = \frac{\sin \frac{2 \times 30}{2}}{2 \sin \frac{30}{2}} = 0.966$$



Winding Factor

- Solution:** $N_l = 2$ $N_{cp} = 4$ $N_{tc} = 10$ $n_r = 3000$ rpm

$$\phi = 0.019 \text{ Wb} \quad p = 2 \quad E_{aa'} = ? \quad E_{rms} = 4.44 N_t f \phi k_w \quad k_w = k_p k_d$$

$$f = 50 \text{ Hz} \quad N_t = 40 \quad k_p = 0.966 \quad k_d = 0.966$$

- The RMS value of the phase induced voltage is

$$E_{rms} = 4.44 \times 40 \times 50 \times 0.019 \times 0.966 \times 0.966$$

$$E_{rms} = 157 \text{ V}$$

