

---

---

*In The Name of God The Most  
Compassionate, The Most Merciful*



# Brushless PM Machines

Design, Optimization and Analysis



# Table of Contents



1. Introduction

2. Magnetic Equivalent Circuit based Modelling

**3. Winding Topology**

4. Two-Dimensional Analytical Modelling

5. Metaheuristic Optimization

6. Numerical Modelling

7. Linear PM Synchronous Machines

# Winding



## Fundamental definitions

### Concentrated vs. distributed winding

- Number of slots per pole per phase  $N_{spp} = \frac{N_s}{2pq}$

where  $N_s$  is the number of slots,  $p$  is the number of pole pairs and  $q$  is the number of phases.

- If  $N_{spp} \geq 1$  the winding is **distributed**
- If  $N_{spp} < 1$  the winding is **concentrated**






# Winding

## Fundamental definitions

### Overlapping vs. non-overlapping windings

- **Non-overlapping**: each coil is wound around a single stator tooth.
  - Alternate teeth wound (Single-layer slots) (a)
  - All teeth wound (double-layer slots) (b)
- **Overlapping**: each coil spans almost a pole pitch. (c)





# Winding

## Fundamental definitions

### Overlapping vs. non-overlapping windings

Advantages of non-overlapping over overlapping windings:

- **Shorter end turn** winding
- Easier **manufacturability**
- More **fault tolerant**, less probability of turn-to-turn short circuit fault.

### Integral vs. fractional

In the case of slotted motors another classification is defined as either *integral* or *fractional* number of slots per pole per phase. Fractional slot structures reduce the cogging torque.



# Winding

## Fundamental definitions

### Winding factors: pitch and distribution factors

- **Pitch factor** for the  $n$ -th harmonic is expressed as

$$k_{pn} = \sin\left(\frac{n\pi\theta_c}{2\theta_p}\right) = \sin\left(\frac{n\theta_c}{2}\right)$$

where  $\theta_c$  is the coil pitch and  $\theta_p$  is the pole pitch both in electrical measures.

- **Distribution factor** for the  $n$ -th harmonic is represented as

$$k_{dn} = \frac{\sin\left(\frac{nm\theta_s}{2}\right)}{m \sin\left(\frac{n\theta_s}{2}\right)}$$

where  $\theta_s = \frac{2\pi p}{N_s}$  is the electrical angle between two adjacent slots and  $m$  is the number of slots in each phase belt.



# Winding Hints

- Winding should **maximize** the **electromagnetic torque** and **minimize** the **torque ripple**.
- The **number of coils** must be a **multiple** number of **phases**.
- The **number of slots** should be a **multiple** number of **phases** for **double-layer** motors. In general  $N_s = kq * 2 / N_l$  where  $q$  is the number of phases and  $N_l$  is the number of layers.
- The **number of slots** must be **even** for **single-layer** windings.
- The **number of poles** must be **even**.



# Winding Hints

- The **number of poles cannot** be equal to the **number of slots**.
- The **phase offset** in slots number should be an integer value

using

$$K_0 = \frac{N_s}{qp} (1 + kq) \quad k = 0, 1, 2, \dots, p-1$$

- In inner rotor motors the **number of poles** is usually **lower** than the **number of slots**.
- In outer rotor motors, it is usual to have **higher number of poles** than the **number of slots**.
- The magnetic **flux linked with each coil** needs to be **maximized** which means the induced back-EMF is maximized.
- The **phase winding** should be **balanced**.





# Winding

## Procedure to find 3-phase layout

1. Select the **number of pole-pairs**,  $p$ . It must be an integer number.
2. Select the **number of layers** for each slot,  $N_l$ . It must be an integer number, normally 1 or 2.
3. Based on the number of pole-pairs and number of layers, select a proper **number of slots**,  $N_s$ .
  - Number of slots should be a **multiple number of phases** for double-layer winding. In general it should be a multiple number of  $q*2/N_l$ .
  - Number of slots should be **even for single layer** winding.
  - The number of slots **cannot** be equal to the number of poles and more generally
$$N_s \neq (q-1)^k 2p \quad k = 0, 1, 2, \dots$$
  - There should be a possibility for **balanced** winding.



# Winding

## Procedure to find 3-phase layout

4. Select between *overlapping* and *non-overlapping* windings.
5. Find **coil pitch** in slot number,  $S$ , using the following expression

$$S = \begin{cases} 1 & \text{for non-overlapping} \\ \max\left(\text{floor}\left(\frac{N_s}{2p}\right), 1\right) & \text{for overlapping} \end{cases}$$

In the case of **single layer** windings,  $S$  should be an **odd** number. If the above expressions results in an even number then  $S=S-1$ .



# Winding

## Procedure to find 3-phase layout

6. Calculate **phase offset** (the offset between two adjacent phases) in terms of slots number,  $K_0$  using the following expression

$$K_0 = \frac{N_s}{qp} (1 + qk) \quad k = 0, 1, 2, \dots, p-1$$

Normally the **first integer value** of  $K_0$  is selected as phase offset. In the case **single layer** winding, phase offset should be an **even** number; therefore the first integer even value is selected as phase offset. Note that if **no integer value** can be found from the above expression, it means the number of **poles/slots** combination is not **valid** for a balanced winding.



# Winding

## Procedure to find 3-phase layout

7. Based on the coil pitch and phase offset the **winding layout** is presented in the following format:

<b>Coil numbers (<math>i</math>)</b>	<b>1</b>	<b>2</b>	<b>...</b>	<b><math>i</math></b>	<b>...</b>	$\frac{N_s N_l}{2}$
<b>Coil angles ( <math>\theta_i^{coil}</math> )</b>	0	$\frac{2\theta_s}{N_l}$	<b>...</b>	$\frac{2\theta_s}{N_l} (i-1)$	<b>...</b>	$\theta_s \left( N_s - \frac{2}{N_l} \right)$
<b>In-slot ( <math>N_i^{in}</math> )</b>	1	$1 + \frac{2}{N_l}$	<b>...</b>	$1 + \frac{2}{N_l} (i-1)$	<b>...</b>	$1 + N_s - \frac{2}{N_l}$
<b>Out-slot ( <math>N_i^{out}</math> )</b>	$1 + S$	$1 + \frac{2}{N_l} + S$	<b>...</b>	$N_i^{in} + S$	<b>...</b>	$1 + N_s - \frac{2}{N_l} + S$

where  $\theta_s = 360 p/N_s$  is the slot pitch angle in electrical degrees.



# Winding

## Procedure to find 3-phase layout

8. **Modify winding layout table** by bringing the coil angles in the range of -180 and 180 and the out-slot between 1 and  $N_s$ :

$$\theta_i^{coil} = \text{rem}(\theta_i^{coil} + 180, 360) - 180$$

$$N_i^{out} = \text{rem}(N_i^{out}, N_s)$$

where *rem* is the remainder function. If  $N_i^{out}$  is zero after applying the remainder function, the zero should be replaced by  $N_s$ .



# Winding

## Procedure to find 3-phase layout

9. For those coils where their coil angles are **greater than 90** degrees or **less than -90 degrees**, the **coil direction is reversed** (swap  $N_i^{in}$  and  $N_i^{out}$ ) and the **coil angles are added by -180 or 180** respectively. By this step, the coil angles are brought within -90 and 90 degrees.


$$\begin{cases} N_i^{in} \leftrightarrow N_i^{out} & \text{if } \theta_i^{coil} > 90 \\ N_i^{in} \leftrightarrow N_i^{out} & \text{if } \theta_i^{coil} < -90 \end{cases}$$

$$\theta_i^{coil} = \begin{cases} \theta_i^{coil} - 180 & \text{if } \theta_i^{coil} > 90 \\ \theta_i^{coil} + 180 & \text{if } \theta_i^{coil} < -90 \end{cases}$$

# Winding

## Procedure to find 3-phase layout

10. Find out **each coil is related to which phase**. To do so, the coils with **coil angles closest to 0** with **minimum total spread** will be selected for the **first phase**. For each coil from first phase there is a corresponding coil for the next phase using the phase offset. This process will be repeated to find the coils of all phases.



# Winding Example 1

Assume a 3-phase machine with

1. **Four poles** (2-pole-pair)
2. **Double layer** slots
3. **15 slots**
4. **Overlapping** winding.


$$q = 3$$

$$p = 2$$

$$N_l = 2$$

$$N_s = 15$$

$$N_{spp} = \frac{N_s}{2qp} = 1.25 \geq 1 \Rightarrow \text{Distributed}$$







# Winding Example 1

## 5. Coil pitch calculation

$$S = \max\left(\text{floor}\left(\frac{N_s}{2p}\right), 1\right) = \max\left(\text{floor}\left(\frac{15}{4}\right), 1\right) = 3$$

## 6. Phase offset calculation

$$\begin{aligned} K_0 &= \frac{N_s}{qp} (1 + qk) & k = 0, 1, 2, \dots, p-1 \\ &= \frac{15}{3 \times 2} (1 + 3k) \\ &= 10 & \text{for } k = 1 \end{aligned}$$



# Winding Example 1

## 7. Winding layout

<b>Coil Numbers</b>	<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>	<b>11</b>	<b>12</b>	<b>13</b>	<b>14</b>	<b>15</b>
<b>Coil angles</b>	0	48	96	144	192	240	288	336	384	432	480	528	576	624	672
<b>In-slot coil</b>	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
<b>Out-slot coil</b>	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18

Coil angles:  $\frac{2\theta_s}{N_l}(i-1)$

In-slot:  $1 + \frac{2}{N_l}(i-1)$

Out-slot:  $N_i^{in} + S$

where  $\theta_s = 360 p / N_s = 48$ ,  $N_l = 2$ ,  $S = 3$



# Winding Example 1

## 8. Modifying winding layout

Coil Numbers	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Coil angles	0	48	96	144	-168	-120	-72	-24	24	72	120	168	-144	-96	-48
In-slot coil	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Out-slot coil	4	5	6	7	8	9	10	11	12	13	14	15	1	2	3

$$\theta_i^{coil} = \text{rem}(\theta_i^{coil} + 180, 360) - 180$$

$$N_i^{out} = \text{rem}(N_i^{out}, N_s)$$



# Winding Example 1

## 9. Modifying winding layout

Coil Numbers	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Coil angles	0	48	-84	-36	12	60	-72	-24	24	72	-60	-12	36	84	-48
In-slot coil	1	2	6	7	8	9	7	8	9	10	14	15	1	2	15
Out-slot coil	4	5	3	4	5	6	10	11	12	13	11	12	13	14	3

$$\theta_i^{coil} = \begin{cases} \theta_i^{coil} - 180 & \& N_i^{in} \leftrightarrow N_i^{out} & \text{if } \theta_i^{coil} > 90 \\ \theta_i^{coil} + 180 & \& N_i^{in} \leftrightarrow N_i^{out} & \text{if } \theta_i^{coil} < -90 \end{cases}$$



# Winding Example 1


10. Find out the coils of each phase (5 coils per phase)

Coil Numbers	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Coil angles	0	48	-84	-36	12	60	-72	-24	24	72	-60	-12	36	84	-48
In-slot coil	1	2	6	7	8	9	7	8	9	10	14	15	1	2	15
Out-slot coil	4	5	3	4	5	6	10	11	12	13	11	12	13	14	3
Phase	A1	C3	B5	B4	A2	C1	B3	A5	A4	C2	B1	A3	C5	C4	B2

# Winding Example 1

Plot the winding topology

Slots	Phase A	Phase B	Phase C
1	In		Out
2			Out & Out
3		In & In	
4	Out	In	
5	Out		In
6		Out	In
7		Out & Out	
8	In & In		
9	In		Out
10		In	Out
11	Out	In	
12	Out & Out		
13			In & In
14		Out	In
15	In	Out	



# Winding

## Valid pole/slot combinations for 2-phase machines



Slots	8	12	16	20	24	28	32	36	40	44	48
Poles	2	2	2	2	2	2	2	2	2	2	2
	6	10	4	6	4	6	4	6	4	6	4
			6	14	6	10	6	10	6	10	6
			10		10	18	8	14	10	14	8
			12		18	22	10	22	12	18	10
			14		20		12	26	14		12
							14	30	26		14
							20		28		18
							22		30		20
							24		34		30
							26				34
							28				36
											38
											40
											42

# Winding

## Valid pole/slot combinations for 3-phase machines



Slots	3	6	9	12	15	18	21	24	27	30	33	36	39	42	45	48
Poles	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2
	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4	4
			6	8	10	6	8	8	6	8	8	6	8	8	6	8
			8	10		8	14	10	8	10	10	8	10	10	8	10
			12	18		12	16	16	10	20	14	10	14	14	10	14
						14		20	12	22	20	12	16	16	12	16
						16			18	26	22	14	26	26	14	20
									20		26	16	28	32	16	32
									22		28	22	32	34	20	34
									24			24	34		28	38
												26			30	40
												28			32	
												30			34	
												32			38	
															40	



# Winding

## Valid pole/slot combinations for 4-phase machines



Slots	8	16	24	32	40	48
Poles	2	2	2	2	2	2
	4	4	6	4	6	4
		6	10	6	10	6
		10	18	8	14	10
		12		10	26	12
		14		12	30	14
				14	34	18
				20		20
				22		30
				24		334
				26		36
				28		38
						40

# Winding

## Valid pole/slot combinations for 5-phase machines



Slots	5	10	15	20	25	30	35	40	45
Poles	2	2	2	2	2	2	2	2	2
	4	4	4	4	4	4	4	4	4
		6	6	6	6	6	6	6	6
		8	12	8	8	8	8	8	8
				12	10	12	12	12	12
				14	16	18	14	14	14
				16	18	22	22	16	16
					20	24	24	24	18
					22	26	26	26	28
							28	28	32
								32	34
								34	36

# Winding

## Valid pole/slot combinations for **6-phase** machines



Slots	12	24	36
Poles	2	2	2
	10	4	6
		10	10
		20	14
			22
			26
			30



# Permitted Current Density

Permitted RMS values for current densities  $J$  and linear current densities  $A$  for various electrical machines. Depending on the size of a permanent magnet machine, a synchronous machine, an asynchronous machine or a DC machine, suitably selected values can be used. Copper windings are generally assumed

	Asynchronous machines	Sailent-pole synchronous machines or PMSMs	Nonsalient-pole synchronous machines			DC machines
			Indirect cooling		Direct water cooling	
			Air	Hydrogen		
$A/\text{kA/m}$	30–65	35–65	30–80	90–110	150–200	25–65
$J/\text{A/mm}^2$	Stator winding	Armature winding		Armature winding		Armature winding
	3–8	4–6.5	3–5	4–6	7–10	4–9
$J/\text{A/mm}^2$	Copper rotor winding	Field winding:				Pole winding
	3–8	2–3.5				2–5.5
$J/\text{A/mm}^2$	Aluminium rotor winding	Multi-layer		Field winding		Compensating winding
	3–6.5	2–4	3–5	3–5	6–12	3–4
		Single-layer	With direct water cooling, in field windings 13–18 A/mm <sup>2</sup> and 250–300 kA/m can be reached			