
*In The Name of God The Most
Compassionate, The Most Merciful*



General Theory of Electric Machines



Table of Contents



1. Introduction

2. Transformers

3. Reference-Frame Theory

4. Induction Machines

5. Synchronous Machines



Chapter 5

Synchronous Machines

5.1. Introduction

5.2. Modelling of Wound Rotor Synchronous Machines

5.3. Simulation of Wound Rotor Synchronous Machines

5.4. Per-Unit System

5.5. Wound Rotor Synchronous Machine Parameters

5.6. Permanent Magnet Synchronous Machines

Introduction




- The construction of 3-phase synchronous machines is relatively **more expensive** than that of induction machines.
- Synchronous machines are **more efficient** compared to the induction machines.
- The **stator** of synchronous machines is **similar** to that of induction machines.
- The synchronous machines are divided in terms of the rotor structures as **salient rotor** and **cylindrical rotor** machines.
- The synchronous machines are also categorized as:
 - **Wound rotor** (electrically excited rotor) synchronous machines,
 - **Permanent magnet** synchronous machines,
 - **Reluctance** synchronous machines.



Various Types of Synchronous Machines


- **Wound rotor** (electrically excited rotor) synchronous machines

- Cylindrical rotor
- Salient rotor




- **Permanent magnet** synchronous machines

- Surface mounted PM (cylindrical rotor)
- Surface inset PM (salient rotor)
- Buried PM (Salient rotor)
 - Radially placed
 - Axially placed
 - inclined



- **Reluctance** synchronous machines

- Segmental rotor
- Flux barrier rotor
- Axially laminated rotor




PM Synchronous Machines

Classification in terms of Magnet structure


Different structures of PM in radial flux PM synchronous motors:

- (a) surface mounted magnet
- (b) surface mounted with parallel edges
- (c) surface mounted ring magnet
- (d) surface mounted bread-loaf magnet
- (e) surface inset magnet
- (f) surface inset magnet with airspace between magnets and iron inter-poles
- (g) buried or interior magnet
- (h) spoke magnet
- (i) multi-segment interior magnet
- (j) multilayer interior magnet



Wound Rotor Synchronous Machines


Circuit Representation



Wound Rotor Synchronous Machines

Circuit Representation


- The stator has a set of **three sinusoidally distributed windings**.
- The rotor has normally one **field winding** which is represented on the d -axis of the frame fixed to the rotor.
- For salient rotor machines, the **dampers** can be represented as two short-circuited damper windings along the d - and q -axis of the frame fixed to the rotor.
- Another winding is considered on the q -axis to represent the effects of **current flow in the rotor iron**.





Wound Rotor Synchronous Machines

Circuit Representation



Wound Rotor Synchronous Machines

Mathematical model: Voltage equations

- The stator-rotor voltage equations can be expressed as:

Rotor

$$v_f = r_f i_f + d\lambda_f / dt$$

$$0 = r_{kd} i_{kd} + d\lambda_{kd} / dt$$

$$v_g = r_g i_g + d\lambda_g / dt$$


$$0 = r_{kq} i_{kq} + d\lambda_{kq} / dt$$

Stator

$$v_{as} = r_s i_{as} + d\lambda_{as} / dt$$

$$v_{bs} = r_s i_{bs} + d\lambda_{bs} / dt$$

$$v_{cs} = r_s i_{cs} + d\lambda_{cs} / dt$$





Wound Rotor Synchronous Machines

Mathematical model: Voltage equations

- The voltage equations can be rewritten in matrix form as follows:

$$\begin{bmatrix} \mathbf{v}_s^{abc} \\ \mathbf{v}_r^{dq} \end{bmatrix} = \begin{bmatrix} \mathbf{r}_s^{abc} & \mathbf{0} \\ \mathbf{0} & \mathbf{r}_r^{dq} \end{bmatrix} \begin{bmatrix} \mathbf{i}_s^{abc} \\ \mathbf{i}_r^{dq} \end{bmatrix} + \frac{d}{dt} \begin{bmatrix} \boldsymbol{\lambda}_s^{abc} \\ \boldsymbol{\lambda}_r^{dq} \end{bmatrix}$$

where

$$\mathbf{r}_s^{abc} = \begin{bmatrix} r_s & 0 & 0 \\ 0 & r_s & 0 \\ 0 & 0 & r_s \end{bmatrix}$$

$$\mathbf{v}_s^{abc} = \begin{bmatrix} v_{as} \\ v_{bs} \\ v_{cs} \end{bmatrix}$$

$$\mathbf{i}_s^{abc} = \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix}$$

$$\boldsymbol{\lambda}_s^{abc} = \begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \\ \lambda_{cs} \end{bmatrix}$$

$$\mathbf{r}_r^{dq} = \begin{bmatrix} r_f & 0 & 0 & 0 \\ 0 & r_{kd} & 0 & 0 \\ 0 & 0 & r_g & 0 \\ 0 & 0 & 0 & r_{kq} \end{bmatrix}$$

$$\mathbf{v}_r^{dq} = \begin{bmatrix} v_f \\ 0 \\ v_g \\ 0 \end{bmatrix}$$

$$\mathbf{i}_r^{dq} = \begin{bmatrix} i_f \\ i_{kd} \\ i_g \\ i_{kq} \end{bmatrix}$$



$$\boldsymbol{\lambda}_r^{dq} = \begin{bmatrix} \lambda_f \\ \lambda_{kd} \\ \lambda_g \\ \lambda_{kq} \end{bmatrix}$$

Wound Rotor Synchronous Machines

Mathematical model: Voltage equations

also

- r_s **stator** or armature winding resistance
- r_f **d-axis field** winding resistance
- r_g **q-axis field** winding resistance
- r_{kd} **d-axis damper** winding resistance
- r_{kq} **q-axis damper** winding resistance



Wound Rotor Synchronous Machines


Mathematical model: Flux linkage equations

- In matrix form, the **flux linkages** of the stator and rotor windings in terms of the winding **inductances** and **currents** are expressed as

$$\begin{bmatrix} \lambda_s^{abc} \\ \lambda_r^{dq} \end{bmatrix} = \begin{bmatrix} \mathbf{L}_{ss}^{abc} & \mathbf{L}_{sr} \\ \mathbf{L}_{rs} & \mathbf{L}_{rr}^{dq} \end{bmatrix} \begin{bmatrix} \mathbf{i}_s^{abc} \\ \mathbf{i}_r^{dq} \end{bmatrix}$$

where

- \mathbf{L}_{ss}^{abc} stator windings inductance matrix
- \mathbf{L}_{rr}^{dq} rotor windings inductance matrix
- $\mathbf{L}_{sr} = [\mathbf{L}_{rs}]^T$ the matrix of mutual inductances between stator and rotor windings





Wound Rotor Synchronous Machines


Mathematical model: Flux linkage equations

- Now the **inductance matrices** have to be represented.
- For **salient rotor** machines, the stator winding inductances in *abc* system **vary with the rotor position**.
- So it is more convenient to obtain the stator winding inductances along the ***d-* and *q-axis*** of the frame fixed to the rotor.
- Also it is assumed that the variation of the stator winding inductances is **sinusoidally**.

$$L_{aa} = \frac{\bar{L}_{md} + \bar{L}_{mq}}{2} - \frac{\bar{L}_{md} - \bar{L}_{mq}}{2} \cos(2\theta_r)$$



$$L_{aa} = L_0 - L_{ms} \cos(2\theta_r)$$





Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

- Assume the **stator winding inductance** matrix in **abc** system is

$$\mathbf{L}_{ss}^{abc} = \begin{bmatrix} L_{aa} & L_{ab} & L_{ac} \\ L_{ba} & L_{bb} & L_{bc} \\ L_{ca} & L_{cb} & L_{cc} \end{bmatrix}$$

- In the following slides, the **stator phase-*a* self inductance** (L_{aa}) without the leakage inductance and the **mutual inductance between phase-*a* and phase-*b*** (L_{ab}) will be obtained.
- The other inductances can be determined in the **same manner**.



Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

Self inductance

- The **stator phase- a self inductance** (L_{aa}) can be calculated using the following expression

$$L_{aa} = \frac{\lambda_{aa}}{i_a}$$

where λ_{aa} is the magnetic flux produced by only the current of phase- a (i_a), linked with the winding of phase- a and obtained as

$$\lambda_{aa} = N_s \phi_a$$

where ϕ_a is the magnetic flux of phase- a and N_s is the number of turns of the winding of phase- a .



Wound Rotor Synchronous Machines


Mathematical model: Flux linkage equations

Self inductance

- ϕ_a is normally calculated by the multiplication of the MMF of phase- a ($F_a = N_s i_a$) and the permeance.
- But the permeance is a **function of the rotor position**.
- Therefore the MMF is resolved along the d - and q - axis as:

$$F_{ad} = F_a \sin \theta_r = N_s i_a \sin \theta_r$$

$$F_{aq} = F_a \cos \theta_r = N_s i_a \cos \theta_r$$





Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

Self inductance


- Now ϕ_{ad} and ϕ_{aq} can be calculated by the multiplication of the corresponding **MMFs** (F_{ad} and F_{aq} respectively) and their related **permeances** (P_d and P_q respectively):

$$\phi_{ad} = P_d F_{ad} = P_d F_a \sin \theta_r$$

$$\phi_{aq} = P_q F_{aq} = P_q F_a \cos \theta_r$$

- ϕ_a is now calculated by the projection of ϕ_{ad} and ϕ_{aq} on a -axis:

$$\phi_a = \phi_{ad} \sin \theta_r + \phi_{aq} \cos \theta_r$$





Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

Self inductance

$$\phi_{ad} = P_d F_a \sin \theta_r$$

$$\phi_{aq} = P_q F_a \cos \theta_r$$

$$\phi_a = \phi_{ad} \sin \theta_r + \phi_{aq} \cos \theta_r$$

$$\phi_a = F_a (P_d \sin^2 \theta_r + P_q \cos^2 \theta_r)$$

where $F_a = N_s i_a$

$$\lambda_{aa} = N_s \phi_a = N_s^2 i_a (P_d \sin^2 \theta_r + P_q \cos^2 \theta_r)$$

$$L_{aa} = \frac{\lambda_{aa}}{i_a} = N_s^2 (P_d \sin^2 \theta_r + P_q \cos^2 \theta_r)$$



Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

Self inductance

$$L_{aa} = N_s^2 (P_d \sin^2 \theta_r + P_q \cos^2 \theta_r)$$

$$\sin^2 \theta_r = \frac{1}{2} (1 - \cos 2\theta_r)$$

$$\cos^2 \theta_r = \frac{1}{2} (1 + \cos 2\theta_r)$$

$$\rightarrow L_{aa} = N_s^2 \left(\frac{P_d + P_q}{2} - \frac{P_d - P_q}{2} \cos 2\theta_r \right)$$

$$\bar{L}_{md} = N_s^2 P_d \quad \bar{L}_{mq} = N_s^2 P_q$$

$$\rightarrow L_{aa} = \frac{\bar{L}_{md} + \bar{L}_{mq}}{2} - \frac{\bar{L}_{md} - \bar{L}_{mq}}{2} \cos (2\theta_r)$$

$$L_0 = \frac{\bar{L}_{md} + \bar{L}_{mq}}{2}$$

$$\rightarrow L_{aa} = L_0 - L_{ms} \cos (2\theta_r)$$

$$L_{ms} = \frac{\bar{L}_{md} - \bar{L}_{mq}}{2}$$



Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

Mutual inductance

$$\phi_{ad} = P_d F_a \sin \theta_r$$

$$\phi_{aq} = P_q F_a \cos \theta_r$$

- Similarly the linkage of the flux components (ϕ_{ad} and ϕ_{aq}) by phase- b winding that is $2\pi/3$ electrical radian ahead can be written as:

$$\lambda_{ab} = N_s \left[\phi_{ad} \sin\left(\theta_r - \frac{2\pi}{3}\right) + \phi_{aq} \cos\left(\theta_r - \frac{2\pi}{3}\right) \right]$$

$$\lambda_{ab} = N_s^2 i_a \left[P_d \sin \theta_r \sin\left(\theta_r - \frac{2\pi}{3}\right) + P_q \cos \theta_r \cos\left(\theta_r - \frac{2\pi}{3}\right) \right]$$

$$L_{ab} = \frac{\lambda_{ab}}{i_a} = N_s^2 \left[P_d \sin \theta_r \sin\left(\theta_r - \frac{2\pi}{3}\right) + P_q \cos \theta_r \cos\left(\theta_r - \frac{2\pi}{3}\right) \right]$$



Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

Mutual inductance

$$L_{ab} = N_s^2 \left[P_d \sin \theta_r \sin \left(\theta_r - \frac{2\pi}{3} \right) + P_q \cos \theta_r \cos \left(\theta_r - \frac{2\pi}{3} \right) \right]$$



$$L_{ab} = N_s^2 \left[-\frac{P_d + P_q}{4} - \frac{P_d - P_q}{2} \cos 2 \left(\theta_r - \frac{\pi}{3} \right) \right]$$


$$\bar{L}_{md} = N_s^2 P_d$$

$$\bar{L}_{mq} = N_s^2 P_q$$



$$L_{ab} = \left[-\frac{\bar{L}_{md} + \bar{L}_{mq}}{4} - \frac{\bar{L}_{md} - \bar{L}_{mq}}{2} \cos 2 \left(\theta_r - \frac{\pi}{3} \right) \right]$$

$$L_0 = \frac{\bar{L}_{md} + \bar{L}_{mq}}{2}$$



$$L_{ab} = -\frac{1}{2} L_0 - L_{ms} \cos 2 \left(\theta_r - \frac{\pi}{3} \right)$$

$$L_{ms} = \frac{\bar{L}_{md} - \bar{L}_{mq}}{2}$$



Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

- Therefore the **stator inductance matrix** with considering the leakage inductance is written as:

$$\mathbf{L}_{ss}^{abc} = \begin{bmatrix} L_{ls} + L_0 - L_{ms} \cos 2\theta_r & -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r - \frac{\pi}{3}) & -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r + \frac{\pi}{3}) \\ -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r - \frac{\pi}{3}) & L_{ls} + L_0 - L_{ms} \cos 2(\theta_r - \frac{2\pi}{3}) & -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r + \pi) \\ -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r + \frac{\pi}{3}) & -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r + \pi) & L_{ls} + L_0 - L_{ms} \cos 2(\theta_r + \frac{2\pi}{3}) \end{bmatrix}$$

- The **rotor inductance matrix** can be expressed as:

$$\mathbf{L}_{rr}^{dq} = \begin{bmatrix} L_{lf} + L_{mf} & L_{fkd} & 0 & 0 \\ L_{kdf} & L_{lkd} + L_{mkd} & 0 & 0 \\ 0 & 0 & L_{lg} + L_{mg} & L_{gkq} \\ 0 & 0 & L_{kqg} & L_{lkq} + L_{mkq} \end{bmatrix}$$

Why?



Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

- The mutual **inductance matrix** between the rotor and stator windings is:

$$\mathbf{L}_{sr} = \begin{bmatrix} L_{sf} \sin \theta_r & L_{skd} \sin \theta_r & L_{sg} \cos \theta_r & L_{skq} \cos \theta_r \\ L_{sf} \sin(\theta_r - \frac{2\pi}{3}) & L_{skd} \sin(\theta_r - \frac{2\pi}{3}) & L_{sg} \cos(\theta_r - \frac{2\pi}{3}) & L_{skq} \cos(\theta_r - \frac{2\pi}{3}) \\ L_{sf} \sin(\theta_r + \frac{2\pi}{3}) & L_{skd} \sin(\theta_r + \frac{2\pi}{3}) & L_{sg} \cos(\theta_r + \frac{2\pi}{3}) & L_{skq} \cos(\theta_r + \frac{2\pi}{3}) \end{bmatrix}$$

$$\mathbf{L}_{rs} = [\mathbf{L}_{sr}]^T$$

Why?

Since both \mathbf{L}_{ss}^{abc} and \mathbf{L}_{rs} are functions of the rotor position, the stator quantities are transformed to the rotor $qd0$ RF.



Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

- L_{ls} stator or armature winding **leakage** inductance
- L_{lf} d -axis field winding **leakage** inductance
- L_{lg} q -axis field winding **leakage** inductance
- L_{lkd} d -axis damper winding **leakage** inductance
- L_{lkq} q -axis damper winding **leakage** inductance
- L_{md} d -axis stator **magnetizing** inductance
- L_{mq} q -axis stator **magnetizing** inductance
- L_{mf} d -axis field winding **magnetizing** inductance
- L_{mg} q -axis field winding **magnetizing** inductance
- L_{mkd} d -axis damper winding **magnetizing** inductance
- L_{mkq} q -axis damper winding **magnetizing** inductance



Wound Rotor Synchronous Machines

Mathematical model: Flux linkage equations

- L_{fkd} **mutual** inductance between d -axis field winding and d -axis damper winding. $L_{kdf} = L_{fkd}$
- L_{gkq} **mutual** inductance between q -axis field winding and q -axis damper winding. $L_{kqg} = L_{gkq}$
- L_{sf} **peak value of mutual** inductance between stator windings and d -axis field winding.
- L_{skd} **peak value of mutual** inductance between stator windings and d -axis damper winding.
- L_{sg} **peak value of mutual** inductance between stator windings and q -axis field winding.
- L_{skq} **peak value of mutual** inductance between stator windings and q -axis damper winding.



Wound Rotor Synchronous Machines

$qd0$ stator voltage equations

- Note that **only the stator quantities** need to be **transformed** to rotor $qd0$ reference frame.
- The transformation is done using:

$$\begin{bmatrix} \mathbf{f}_{qd0} \end{bmatrix} = \begin{bmatrix} \mathbf{T}_{qd0}(\theta_r) \end{bmatrix} \begin{bmatrix} \mathbf{f}_{abc} \end{bmatrix} \quad \begin{bmatrix} \mathbf{f}_{abc} \end{bmatrix} = \begin{bmatrix} \mathbf{T}_{qd0}(\theta_r) \end{bmatrix}^{-1} \begin{bmatrix} \mathbf{f}_{qd0} \end{bmatrix}$$

where

$$\begin{bmatrix} \mathbf{T}_{qd0}(\theta_r) \end{bmatrix} = \frac{2}{3} \begin{bmatrix} \cos \theta_r & \cos \left(\theta_r - \frac{2\pi}{3} \right) & \cos \left(\theta_r + \frac{2\pi}{3} \right) \\ \sin \theta_r & \sin \left(\theta_r - \frac{2\pi}{3} \right) & \sin \left(\theta_r + \frac{2\pi}{3} \right) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix}$$

$$\begin{bmatrix} \mathbf{T}_{qd0}(\theta_r) \end{bmatrix}^{-1} = \begin{bmatrix} \cos \theta_r & \sin \theta_r & 1 \\ \cos \left(\theta_r - \frac{2\pi}{3} \right) & \sin \left(\theta_r - \frac{2\pi}{3} \right) & 1 \\ \cos \left(\theta_r + \frac{2\pi}{3} \right) & \sin \left(\theta_r + \frac{2\pi}{3} \right) & 1 \end{bmatrix}$$



Wound Rotor Synchronous Machines

$qd0$ stator voltage equations

- The stator voltage equations in abc system are

$$\mathbf{v}_s^{abc} = \mathbf{r}_s^{abc} \mathbf{i}_s^{abc} + p \boldsymbol{\lambda}_s^{abc} \quad \text{where } p = d/dt$$

$$\mathbf{f}_{abc} = \mathbf{T}_{qd0}(\theta_r)^{-1} \mathbf{f}_{qd0}$$

- Applying the transformation $\mathbf{T}_{qd0}(\theta_r)$ to the voltage, current and flux yields

$$\mathbf{T}_{qd0}(\theta_r)^{-1} \mathbf{v}_s^{qd0} = \mathbf{r}_s^{abc} \mathbf{T}_{qd0}(\theta_r)^{-1} \mathbf{i}_s^{qd0} + p \left(\mathbf{T}_{qd0}(\theta_r)^{-1} \boldsymbol{\lambda}_s^{qd0} \right)$$

- Multiplying both sides by the transformation matrix yields

$$\mathbf{v}_s^{qd0} = \mathbf{T}_{qd0}(\theta_r) \mathbf{r}_s^{abc} \mathbf{T}_{qd0}(\theta_r)^{-1} \mathbf{i}_s^{qd0} + \mathbf{T}_{qd0}(\theta_r) p \left(\mathbf{T}_{qd0}(\theta_r)^{-1} \boldsymbol{\lambda}_s^{qd0} \right)$$



Wound Rotor Synchronous Machines

qd0 stator voltage equations

$$\mathbf{v}_s^{qd0} = \mathbf{r}_s^{qd0} \mathbf{i}_s^{qd0} + \left[\mathbf{T}_{qd0}(\theta_r) \right] p \left(\left[\mathbf{T}_{qd0}(\theta_r) \right]^{-1} \boldsymbol{\lambda}_s^{qd0} \right)$$

- Substituting the following relations in the above expression

$$\mathbf{r}_s^{qd0} = \mathbf{r}_s^{abc} = r_s \begin{bmatrix} 1 & 0 & 0 \\ 0 & 1 & 0 \\ 0 & 0 & 1 \end{bmatrix} \quad \left[\mathbf{T}_{qd0}(\theta_r) \right] p \left(\left[\mathbf{T}_{qd0}(\theta_r) \right]^{-1} \boldsymbol{\lambda}_s^{qd0} \right) = \omega_r \begin{bmatrix} 0 & 1 & 0 \\ -1 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix} \boldsymbol{\lambda}_s^{qd0} + p \boldsymbol{\lambda}_s^{qd0}$$

yields

$$\mathbf{v}_s^{qd0} = \mathbf{r}_s^{qd0} \mathbf{i}_s^{qd0} + \omega_r \begin{bmatrix} 0 & 1 & 0 \\ -1 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix} \boldsymbol{\lambda}_s^{qd0} + p \boldsymbol{\lambda}_s^{qd0}$$



Wound Rotor Synchronous Machines

$qd0$ stator voltage equations

$qd0$ stator voltage equations

$$\mathbf{v}_s^{qd0} = \underbrace{\mathbf{r}_s^{qd0} \mathbf{i}_s^{qd0}}_{\text{Ohmic drop}} + \underbrace{\omega_r \begin{bmatrix} 0 & 1 & 0 \\ -1 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix} \boldsymbol{\lambda}_s^{qd0}}_{\text{Rotational EMF}} + \underbrace{p \boldsymbol{\lambda}_s^{qd0}}_{\text{Transformer EMF}}$$

$$\mathbf{v}_s^{qd0} = \begin{bmatrix} v_{qs} \\ v_{ds} \\ v_{0s} \end{bmatrix}$$

$$\mathbf{i}_s^{qd0} = \begin{bmatrix} i_{qs} \\ i_{ds} \\ i_{0s} \end{bmatrix}$$

$$\boldsymbol{\lambda}_s^{qd0} = \begin{bmatrix} \lambda_{qs} \\ \lambda_{ds} \\ \lambda_{0s} \end{bmatrix}$$

$$\begin{cases} v_{qs} = r_s i_{qs} + p \lambda_{qs} + \omega_r \lambda_{ds} \\ v_{ds} = r_s i_{ds} + p \lambda_{ds} - \omega_r \lambda_{qs} \\ v_{0s} = r_s i_{0s} + p \lambda_{0s} \end{cases}$$



Wound Rotor Synchronous Machines

$qd0$ stator flux linkage equations

- The **stator flux linkage** equations in abc system is expressed as:

$$\boldsymbol{\lambda}_s^{abc} = \mathbf{L}_{ss}^{abc} \mathbf{i}_s^{abc} + \mathbf{L}_{sr} \mathbf{i}_r^{dq}$$

$$\mathbf{f}_{abc} = \mathbf{T}_{qd0}(\theta_r)^{-1} \mathbf{f}_{qd0}$$

- Applying the transformation $\mathbf{T}_{qd0}(\theta_r)$ to the stator quantities yields

$$\mathbf{T}_{qd0}(\theta_r)^{-1} \boldsymbol{\lambda}_s^{qd0} = \mathbf{L}_{ss}^{abc} \mathbf{T}_{qd0}(\theta_r)^{-1} \mathbf{i}_s^{qd0} + \mathbf{L}_{sr} \mathbf{i}_r^{dq}$$

- Multiplying both sides by $\mathbf{T}_{qd0}(\theta_r)$ yields

$$\boldsymbol{\lambda}_s^{qd0} = \mathbf{T}_{qd0}(\theta_r) \mathbf{L}_{ss}^{abc} \mathbf{T}_{qd0}(\theta_r)^{-1} \mathbf{i}_s^{qd0} + \mathbf{T}_{qd0}(\theta_r) \mathbf{L}_{sr} \mathbf{i}_r^{dq}$$



Wound Rotor Synchronous Machines

$qd0$ stator flux linkage equations

$$\lambda_s^{qd0} = \underbrace{[\mathbf{T}_{qd0}(\theta_r)] \mathbf{L}_{ss}^{abc} [\mathbf{T}_{qd0}(\theta_r)]^{-1}}_{\mathbf{L}_{ss}^{qd0}} \mathbf{i}_s^{qd0} + \underbrace{[\mathbf{T}_{qd0}(\theta_r)] \mathbf{L}_{sr}}_{\mathbf{L}_{sr}^{qd0}} \mathbf{i}_r^{dq}$$



$$\lambda_s^{qd0} = \mathbf{L}_{ss}^{qd0} \mathbf{i}_s^{qd0} + \mathbf{L}_{sr}^{qd0} \mathbf{i}_r^{dq}$$

The inductance matrices L_{ss} and L_{sr} in $qd0$ reference frame need to be obtained.



Wound Rotor Synchronous Machines

$qd0$ stator flux linkage equations

$$\mathbf{L}_{ss}^{abc} = \begin{bmatrix} L_{ls} + L_0 - L_{ms} \cos 2\theta_r & -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r - \frac{\pi}{3}) & -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r + \frac{\pi}{3}) \\ -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r - \frac{\pi}{3}) & L_{ls} + L_0 - L_{ms} \cos 2(\theta_r - \frac{2\pi}{3}) & -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r + \pi) \\ -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r + \frac{\pi}{3}) & -\frac{1}{2} L_0 - L_{ms} \cos 2(\theta_r + \pi) & L_{ls} + L_0 - L_{ms} \cos 2(\theta_r + \frac{2\pi}{3}) \end{bmatrix}$$

where $\mathbf{L}_{ss}^{qd0} = [\mathbf{T}_{qd0}(\theta_r)] \mathbf{L}_{ss}^{abc} [\mathbf{T}_{qd0}(\theta_r)]^{-1}$ is the **stator self-inductance** matrix in $qd0$ reference frame

$$\mathbf{L}_{ss}^{qd0} = \begin{bmatrix} L_{ls} + \frac{3}{2}(L_0 - L_{ms}) & 0 & 0 \\ 0 & L_{ls} + \frac{3}{2}(L_0 + L_{ms}) & 0 \\ 0 & 0 & L_{ls} \end{bmatrix}$$

Diagonal matrix and independent of θ_r .



Wound Rotor Synchronous Machines

$qd0$ stator flux linkage equations

$$\mathbf{L}_{sr} = \begin{bmatrix} L_{sf} \sin \theta_r & L_{skd} \sin \theta_r & L_{sg} \cos \theta_r & L_{skq} \cos \theta_r \\ L_{sf} \sin(\theta_r - \frac{2\pi}{3}) & L_{skd} \sin(\theta_r - \frac{2\pi}{3}) & L_{sg} \cos(\theta_r - \frac{2\pi}{3}) & L_{skq} \cos(\theta_r - \frac{2\pi}{3}) \\ L_{sf} \sin(\theta_r + \frac{2\pi}{3}) & L_{skd} \sin(\theta_r + \frac{2\pi}{3}) & L_{sg} \cos(\theta_r + \frac{2\pi}{3}) & L_{skq} \cos(\theta_r + \frac{2\pi}{3}) \end{bmatrix}$$

and $\mathbf{L}_{sr}^{qd0} = [\mathbf{T}_{qd0}(\theta_r)] \mathbf{L}_{sr}$ is the **stator-to-rotor mutual**

inductance matrix in $qd0$ reference frame

$$\mathbf{L}_{sr}^{qd0} = \begin{bmatrix} 0 & 0 & L_{sg} & L_{skq} \\ L_{sf} & L_{skd} & 0 & 0 \\ 0 & 0 & 0 & 0 \end{bmatrix}$$

Matrix is
independent of θ_r .



Wound Rotor Synchronous Machines

$qd0$ rotor flux linkage equations

- The **rotor flux linkage** equations in dq RF is expressed as:

$$\lambda_r^{dq} = \mathbf{L}_{rs} \mathbf{i}_s^{abc} + \mathbf{L}_{rr}^{dq} \mathbf{i}_r^{dq}$$

$$[\mathbf{f}_{abc}] = [\mathbf{T}_{qd0}(\theta_r)]^{-1} [\mathbf{f}_{qd0}]$$

- Applying the transformation $\mathbf{T}_{qd0}(\theta_r)$ to the stator current yields

$$\lambda_r^{dq} = \underbrace{\mathbf{L}_{rs} [\mathbf{T}_{qd0}(\theta_r)]^{-1}}_{\mathbf{L}_{rs}^{qd0}} \mathbf{i}_s^{qd0} + \mathbf{L}_{rr}^{dq} \mathbf{i}_r^{dq}$$

$$\mathbf{L}_{rs}^{qd0} = \begin{bmatrix} 0 & \frac{3}{2} L_{sf} & 0 \\ 0 & \frac{3}{2} L_{skd} & 0 \\ \frac{3}{2} L_{sg} & 0 & 0 \\ \frac{3}{2} L_{skq} & 0 & 0 \end{bmatrix} = \frac{3}{2} [\mathbf{L}_{sr}^{qd0}]^T$$

$$\lambda_r^{dq} = \mathbf{L}_{rs}^{qd0} \mathbf{i}_s^{qd0} + \mathbf{L}_{rr}^{dq} \mathbf{i}_r^{dq}$$



Wound Rotor Synchronous Machines

flux linkage equations

$$\lambda_s^{qd0} = \mathbf{L}_{ss}^{qd0} \mathbf{i}_s^{qd0} + \mathbf{L}_{sr}^{qd0} \mathbf{i}_r^{dq}$$

&

$$\lambda_r^{dq} = \mathbf{L}_{rs}^{qd0} \mathbf{i}_s^{qd0} + \mathbf{L}_{rr}^{dq} \mathbf{i}_r^{dq}$$



$$\begin{bmatrix} \lambda_{qs} \\ \lambda_{ds} \\ \lambda_{0s} \\ \lambda_f \\ \lambda_{kd} \\ \lambda_g \\ \lambda_{kq} \end{bmatrix} = \begin{bmatrix} L_{ls} + L_{mq} & 0 & 0 & 0 & 0 & L_{sg} & L_{skq} \\ 0 & L_{ls} + L_{md} & 0 & L_{sf} & L_{skd} & 0 & 0 \\ 0 & 0 & L_{ls} & 0 & 0 & 0 & 0 \\ 0 & \frac{3}{2} L_{sf} & 0 & L_{lf} + L_{mf} & L_{fkd} & 0 & 0 \\ 0 & \frac{3}{2} L_{skd} & 0 & L_{kdf} & L_{lkd} + L_{mkd} & 0 & 0 \\ \frac{3}{2} L_{sg} & 0 & 0 & 0 & 0 & L_{lg} + L_{mg} & L_{gkq} \\ \frac{3}{2} L_{skq} & 0 & 0 & 0 & 0 & L_{kqg} & L_{lkq} + L_{mkq} \end{bmatrix} \begin{bmatrix} i_{qs} \\ i_{ds} \\ i_{0s} \\ i_f \\ i_{kd} \\ i_g \\ i_{kq} \end{bmatrix}$$

where $L_{md} = \frac{3}{2}(L_0 + L_{ms}) = \frac{3}{2}N_s^2 P_d$ and $L_{mq} = \frac{3}{2}(L_0 - L_{ms}) = \frac{3}{2}N_s^2 P_q$ are the **equivalent magnetizing inductances** of the d - and q -axis stator winding respectively.



Wound Rotor Synchronous Machines

flux linkage equations

- As evident, the inductance matrix is **non-symmetric** due to the presence of 3/2 factor. Replacing the actual rotor currents with the following **equivalent currents**

$$\hat{i}_f = \frac{2}{3} i_f$$

$$\hat{i}_{kd} = \frac{2}{3} i_{kd}$$

$$\hat{i}_g = \frac{2}{3} i_g$$

$$\hat{i}_{kq} = \frac{2}{3} i_{kq}$$

yields

$$\begin{bmatrix} \lambda_{qs} \\ \lambda_{ds} \\ \lambda_{0s} \\ \lambda_f \\ \lambda_{kd} \\ \lambda_g \\ \lambda_{kq} \end{bmatrix} = \begin{bmatrix} L_{ls} + L_{mq} & 0 & 0 & 0 & 0 & \frac{3}{2} L_{sg} & \frac{3}{2} L_{skq} \\ 0 & L_{ls} + L_{md} & 0 & \frac{3}{2} L_{sf} & \frac{3}{2} L_{skd} & 0 & 0 \\ 0 & 0 & L_{ls} & 0 & 0 & 0 & 0 \\ \hline 0 & \frac{3}{2} L_{sf} & 0 & \frac{3}{2} (L_{lf} + L_{mf}) & \frac{3}{2} L_{fkd} & 0 & 0 \\ 0 & \frac{3}{2} L_{skd} & 0 & \frac{3}{2} L_{kdf} & \frac{3}{2} (L_{lkd} + L_{mkd}) & 0 & 0 \\ \frac{3}{2} L_{sg} & 0 & 0 & 0 & 0 & \frac{3}{2} (L_{lg} + L_{mg}) & \frac{3}{2} L_{gkq} \\ \frac{3}{2} L_{skq} & 0 & 0 & 0 & 0 & \frac{3}{2} L_{kqg} & \frac{3}{2} (L_{lkq} + L_{mkq}) \end{bmatrix} \begin{bmatrix} i_{qs} \\ i_{ds} \\ i_{0s} \\ \hat{i}_f \\ \hat{i}_{kd} \\ \hat{i}_g \\ \hat{i}_{kq} \end{bmatrix}$$



Wound Rotor Synchronous Machines

Referring rotor quantities to the stator side

- Now all the rotor quantities and parameters are referred to the stator side:

$$i'_f = \frac{N_f}{N_s} \hat{i}_f = \frac{2}{3} \frac{N_f}{N_s} i_f$$

$$i'_{kd} = \frac{N_{kd}}{N_s} \hat{i}_{kd} = \frac{2}{3} \frac{N_{kd}}{N_s} i_{kd}$$

$$v'_f = \frac{N_s}{N_f} v_f$$

$$v'_{kd} = \frac{N_s}{N_{kd}} v_{kd}$$

$$i'_g = \frac{N_g}{N_s} \hat{i}_g = \frac{2}{3} \frac{N_g}{N_s} i_g$$

$$i'_{kq} = \frac{N_{kq}}{N_s} \hat{i}_{kq} = \frac{2}{3} \frac{N_{kq}}{N_s} i_{kq}$$

$$v'_g = \frac{N_s}{N_g} v_g$$

$$v'_{kq} = \frac{N_s}{N_{kq}} v_{kq}$$

$$\lambda'_f = \frac{N_s}{N_f} \lambda_f$$

$$\lambda'_{kd} = \frac{N_s}{N_{kd}} \lambda_{kd}$$

$$r'_f = \frac{3}{2} \left(\frac{N_s}{N_f} \right)^2 r_f$$

$$r'_{kd} = \frac{3}{2} \left(\frac{N_s}{N_{kd}} \right)^2 r_{kd}$$

$$\lambda'_g = \frac{N_s}{N_g} \lambda_g$$

$$\lambda'_{kq} = \frac{N_s}{N_{kq}} \lambda_{kq}$$

$$r'_g = \frac{3}{2} \left(\frac{N_s}{N_g} \right)^2 r_g$$

$$r'_{kq} = \frac{3}{2} \left(\frac{N_s}{N_{kq}} \right)^2 r_{kq}$$



Wound Rotor Synchronous Machines

Referring rotor quantities to the stator side

$$L_{md} = \frac{3}{2} N_s^2 P_d$$

$$L_{mq} = \frac{3}{2} N_s^2 P_q$$

- Using the above relations, the inductances are expressed as:

Mutual inductances
between rotor and
stator windings:

$$L_{sf} = N_s N_f P_d = \frac{2}{3} \frac{N_f}{N_s} L_{md}$$

$$L_{skd} = N_s N_{kd} P_d = \frac{2}{3} \frac{N_{kd}}{N_s} L_{md}$$

$$L_{sg} = N_s N_g P_q = \frac{2}{3} \frac{N_g}{N_s} L_{mq}$$

$$L_{skq} = N_s N_{kq} P_q = \frac{2}{3} \frac{N_{kq}}{N_s} L_{mq}$$

Magnetizing
inductances of the
rotor windings:

$$L_{mf} = N_f^2 P_d = \frac{2}{3} \left(\frac{N_f}{N_s} \right)^2 L_{md}$$

$$L_{mkd} = N_{kd}^2 P_d = \frac{2}{3} \left(\frac{N_{kd}}{N_s} \right)^2 L_{md}$$

$$L_{mg} = N_g^2 P_q = \frac{2}{3} \left(\frac{N_g}{N_s} \right)^2 L_{mq}$$

$$L_{mkq} = N_{kq}^2 P_q = \frac{2}{3} \left(\frac{N_{kq}}{N_s} \right)^2 L_{mq}$$



Wound Rotor Synchronous Machines

Referring rotor quantities to the stator side

$$L_{md} = \frac{3}{2} N_s^2 P_d$$

$$L_{mq} = \frac{3}{2} N_s^2 P_q$$

- Using the above relations, the inductances are expressed as:

**Mutual inductances between
d-axis rotor windings
(between *f* and *kd*):**

$$L_{fkd} = L_{kdf} = N_f N_{kd} P_d = \frac{2}{3} \frac{N_f N_{kd}}{N_s^2} L_{md}$$

**Mutual inductances between
q-axis rotor windings
(between *g* and *kq*):**

$$L_{gkq} = L_{kqg} = N_g N_{kq} P_d = \frac{2}{3} \frac{N_g N_{kq}}{N_s^2} L_{mq}$$



Wound Rotor Synchronous Machines

Referring rotor quantities to the stator side

- The remaining rotor parameters are referred to the stator side:

$$L'_{ff} = \frac{3}{2} \left(\frac{N_s}{N_f} \right)^2 L_{lf} + L_{md}$$

$$L'_{kdkd} = \frac{3}{2} \left(\frac{N_s}{N_{kd}} \right)^2 L_{lkd} + L_{md}$$

$$L'_{gg} = \frac{3}{2} \left(\frac{N_s}{N_g} \right)^2 L_{lg} + L_{mq}$$

$$L'_{kqkq} = \frac{3}{2} \left(\frac{N_s}{N_{kq}} \right)^2 L_{lkq} + L_{mq}$$

- The d - and q -axis **synchronous inductances** are defined as:

$$L_d = L_{ls} + L_{md}$$

$$L_q = L_{ls} + L_{mq}$$



Wound Rotor Synchronous Machines

$qd0$ flux linkage equations referred to the stator side

$$\begin{bmatrix} \lambda_{qs} \\ \lambda_{ds} \\ \lambda_{0s} \\ \lambda'_f \\ \lambda'_{kd} \\ \lambda'_g \\ \lambda'_{kq} \end{bmatrix} = \begin{bmatrix} L_q & 0 & 0 & 0 & 0 & L_{mq} & L_{mq} \\ 0 & L_d & 0 & L_{md} & L_{md} & 0 & 0 \\ 0 & 0 & L_{ls} & 0 & 0 & 0 & 0 \\ 0 & L_{md} & 0 & L'_{ff} & L_{md} & 0 & 0 \\ 0 & L_{md} & 0 & L_{md} & L'_{kdkd} & 0 & 0 \\ L_{mq} & 0 & 0 & 0 & 0 & L'_{gg} & L_{mq} \\ L_{mq} & 0 & 0 & 0 & 0 & L_{mq} & L'_{kqkq} \end{bmatrix} \begin{bmatrix} i_{qs} \\ i_{ds} \\ i_{0s} \\ i'_f \\ i'_{kd} \\ i'_g \\ i'_{kq} \end{bmatrix}$$

$$L'_{ff} = \frac{3}{2} \left(\frac{N_s}{N_f} \right)^2 L_{lf} + L_{md}$$

$$L'_{gg} = \frac{3}{2} \left(\frac{N_s}{N_g} \right)^2 L_{lg} + L_{mq}$$

$$L'_{kdkd} = \frac{3}{2} \left(\frac{N_s}{N_{kd}} \right)^2 L_{lkd} + L_{md}$$

$$L'_{kqkq} = \frac{3}{2} \left(\frac{N_s}{N_{kq}} \right)^2 L_{lkq} + L_{mq}$$

$$L_d = L_{ls} + L_{md}$$

$$L_{sf} = \frac{2}{3} \frac{N_f}{N_s} L_{md}$$

$$L_{sg} = \frac{2}{3} \frac{N_g}{N_s} L_{mq}$$

$$L_{gkq} = L_{kqg} = \frac{2}{3} \frac{N_g N_{kq}}{N_s^2} L_{mq}$$

$$L_q = L_{ls} + L_{mq}$$

$$L_{skd} = \frac{2}{3} \frac{N_{kd}}{N_s} L_{md}$$

$$L_{skq} = \frac{2}{3} \frac{N_{kq}}{N_s} L_{mq}$$

$$L_{fkd} = L_{kdf} = \frac{2}{3} \frac{N_f N_{kd}}{N_s^2} L_{md}$$



Wound Rotor Synchronous Machines


Summary: $qd0$ equations referred to the stator side

Stator

$$v_{qs} = r_s i_{qs} + d\lambda_{qs}/dt + \omega_r \lambda_{ds}$$

$$v_{ds} = r_s i_{ds} + d\lambda_{ds}/dt - \omega_r \lambda_{qs}$$

$$v_{0s} = r_s i_{0s} + d\lambda_{0s}/dt$$



Rotor

$$v'_f = r'_f i'_f + d\lambda'_f/dt$$

$$v'_{kd} = r'_{kd} i'_{kd} + d\lambda'_{kd}/dt$$

$$v'_g = r'_g i'_g + d\lambda'_g/dt$$

$$v'_{kq} = r'_{kq} i'_{kq} + d\lambda'_{kq}/dt$$

$$\lambda_{qs} = L_q i_{qs} + L_{mq} i'_g + L_{mq} i'_{kq}$$

$$\lambda_{ds} = L_d i_{ds} + L_{md} i'_f + L_{md} i'_{kd}$$

$$\lambda_{0s} = L_{ls} i_{0s}$$

$$\lambda'_f = L_{md} i_{ds} + L'_{ff} i'_f + L_{md} i'_{kd}$$

$$\lambda'_{kd} = L_{md} i_{ds} + L_{md} i'_f + L'_{kdkd} i'_{kd}$$

$$\lambda'_g = L_{mq} i_{qs} + L'_{gg} i'_g + L_{mq} i'_{kq}$$

$$\lambda'_{kq} = L_{mq} i_{qs} + L_{mq} i'_g + L'_{kqkq} i'_{kq}$$

43



Wound Rotor Synchronous Machines

q-axis equivalent circuit

Stator

Rotor

$$v_{qs} = r_s i_{qs} + d\lambda_{qs} / dt + \omega \lambda_{ds}$$


$$\lambda_{qs} = L_{ls} i_{qs} + L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$\lambda'_g = L'_{lg} i'_g + L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$\lambda'_{kq} = L'_{lkq} i'_{kq} + L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$v'_g = r'_g i'_g + d\lambda'_g / dt$$

$$v'_{kq} = r'_{kq} i'_{kq} + d\lambda'_{kq} / dt$$





Wound Rotor Synchronous Machines

d-axis equivalent circuit

Stator


$$v_{ds} = r_s i_{ds} + d\lambda_{ds}/dt - \omega \lambda_{qs}$$

$$\lambda_{ds} = L_{ls} i_{ds} + L_{md} (i_{ds} + i'_f + i'_{kd})$$

Rotor

$$\lambda'_f = L'_{lf} i'_f + L_{md} (i_{ds} + i'_f + i'_{kd})$$

$$\lambda'_{kd} = L'_{lkd} i'_{kd} + L_{md} (i_{ds} + i'_f + i'_{kd})$$



$$v'_f = r'_f i'_f + d\lambda'_f / dt$$

$$v'_{kd} = r'_{kd} i'_{kd} + d\lambda'_{kd} / dt$$



Wound Rotor Synchronous Machines

Zero-component equivalent circuit

Stator

$$v_{0s} = r_s i_{0s} + d\lambda_{0s}/dt$$

$$\lambda_{0s} = L_{ls} i_{0s}$$





Wound Rotor Synchronous Machines

Torque Equation

- The instantaneous input power is obtained as

$$P_{in} = v_{as} i_{as} + v_{bs} i_{bs} + v_{cs} i_{cs} + v_f i_f + v_g i_g$$

- In terms of qd0 quantities, the instantaneous input power is

$$P_{in} = \frac{3}{2} (v_{qs} i_{qs} + v_{ds} i_{ds}) + 3v_{0s} i_{0s} + v_f i_f + v_g i_g$$

- Substituting the voltage equations in the above expression yields

$$P_{in} = \frac{3}{2} (r_s i_{qs}^2 + i_{qs} p \lambda_{qs} + \omega_r \lambda_{ds} i_{qs} + r_s i_{ds}^2 + i_{ds} p \lambda_{ds} - \omega_r \lambda_{qs} i_{ds}) \\ + 3r_s i_{0s}^2 + 3i_{0s} p \lambda_{0s} + r_f i_f^2 + i_f p \lambda_f + r_g i_g^2 + i_g p \lambda_g$$



Wound Rotor Synchronous Machines

Torque Equation

$$P_{in} = \frac{3}{2} \left(r_s i_{qs}^2 + i_{qs} p \lambda_{qs} + \omega_r \lambda_{ds} i_{qs} + r_s i_{ds}^2 + i_{ds} p \lambda_{ds} - \omega_r \lambda_{qs} i_{ds} \right) \\ + 3r_s i_{0s}^2 + 3i_{0s} p \lambda_{0s} + r_f i_f^2 + i_f p \lambda_f + r_g i_g^2 + i_g p \lambda_g$$

- The **ohmic losses** (ri^2 terms) and the **rate of exchange of magnetic field energy** between windings ($ip\lambda$ terms) **do not contribute** to electromagnetic (EM) torque development.
- Hence the **power terms contributed** to EM torque generation are:

$$P_T = \frac{3}{2} \omega_r \left(\lambda_{ds} i_{qs} - \lambda_{qs} i_{ds} \right)$$



Wound Rotor Synchronous Machines

Torque Equation

$$P_T = \frac{3}{2} \omega_r (\lambda_{ds} i_{qs} - \lambda_{qs} i_{ds})$$

- The electromagnetic torque is obtained by dividing the above power by the **mechanical speed**.

$$T_{em} = \frac{3}{2} \frac{P}{2} (\lambda_{ds} i_{qs} - \lambda_{qs} i_{ds})$$

where P is the number of poles.

- The relation between the mechanical speed and the electrical speed is as follows:

$$\omega_{rm} = \frac{2}{P} \omega_r$$



Wound Rotor Synchronous Machines

Mechanical Dynamic Equation

- Based on Newton's 2nd law for rotational movement, $\sum T = J \frac{d\omega_{rm}}{dt}$ the **mechanical dynamic equation** is obtained:

Motoring Mode

$$T_{em} - T_{mech} - T_{damp} = J \frac{d\omega_{rm}}{dt}$$

Generating Mode

$$T_{em} + T_{mech} - T_{damp} = J \frac{d\omega_{rm}}{dt}$$

where T_{mech} is the externally-applied mechanical torque, T_{damp} is the damping torque, J is the moment of inertia and ω_{rm} is the mechanical rotational velocity.




Wound Rotor Synchronous Machines

Currents in terms of flux linkages

- Synchronous machines can be simulated using the **flux linkages as the state variables**.
- Hence it is required to obtain the **currents in terms of flux linkages**.
- Let's define the following **mutual flux linkages** in the q - and d -axis:

$$\lambda_{mq} = L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$\lambda_{md} = L_{md} (i_{ds} + i'_f + i'_{kd})$$





Wound Rotor Synchronous Machines

Currents in terms of flux linkages

- The following expressions for **q-axis currents** can be obtained:

$$\lambda_{qs} = L_{ls} i_{qs} + L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$\lambda_{mq} = L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$i_{qs} = \frac{1}{L_{ls}} (\lambda_{qs} - \lambda_{mq})$$

$$\lambda'_g = L'_{lg} i'_g + L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$\lambda_{mq} = L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$i'_g = \frac{1}{L'_{lg}} (\lambda'_g - \lambda_{mq})$$

$$\lambda'_{kq} = L'_{lkq} i'_{kq} + L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$\lambda_{mq} = L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$i'_{kq} = \frac{1}{L'_{lkq}} (\lambda'_{kq} - \lambda_{mq})$$



Wound Rotor Synchronous Machines

Currents in terms of flux linkages

- The following expressions for **d-axis currents** can be obtained:

$$\lambda_{ds} = L_{ls} i_{ds} + L_{md} (i_{ds} + i'_f + i'_{kd})$$

$$\lambda_{md} = L_{md} (i_{ds} + i'_f + i'_{kd})$$

$$i_{ds} = \frac{1}{L_{ls}} (\lambda_{ds} - \lambda_{md})$$

$$\lambda'_f = L'_{lf} i'_f + L_{md} (i_{ds} + i'_f + i'_{kd})$$

$$\lambda_{md} = L_{md} (i_{ds} + i'_f + i'_{kd})$$

$$i'_f = \frac{1}{L'_{lf}} (\lambda'_f - \lambda_{md})$$

$$\lambda'_{kd} = L'_{lkd} i'_{kd} + L_{md} (i_{ds} + i'_f + i'_{kd})$$

$$\lambda_{md} = L_{md} (i_{ds} + i'_f + i'_{kd})$$

$$i'_{kd} = \frac{1}{L'_{lkd}} (\lambda'_{kd} - \lambda_{md})$$



Wound Rotor Synchronous Machines

Currents in terms of flux linkages

- Substituting the expressions of the q -axis winding currents in the q -axis mutual flux linkages yields:

$$\lambda_{mq} = L_{mq} (i_{qs} + i'_g + i'_{kq})$$

$$i_{qs} = \frac{1}{L_{ls}} (\lambda_{qs} - \lambda_{mq})$$

$$i'_g = \frac{1}{L'_{lg}} (\lambda'_g - \lambda_{mq})$$

$$i'_{kq} = \frac{1}{L'_{lkq}} (\lambda'_{kq} - \lambda_{mq})$$



$$\lambda_{mq} = L_{MQ} \left(\frac{\lambda_{qs}}{L_{ls}} + \frac{\lambda'_g}{L'_{lg}} + \frac{\lambda'_{kq}}{L'_{lkq}} \right)$$

where

$$\frac{1}{L_{MQ}} = \frac{1}{L_{ls}} + \frac{1}{L'_{lg}} + \frac{1}{L'_{lkq}} + \frac{1}{L_{mq}}$$



Wound Rotor Synchronous Machines

Currents in terms of flux linkages

- Substituting the expressions of the d -axis winding currents in the d -axis mutual flux linkages yields:

$$\lambda_{md} = L_{md} (i_{ds} + i'_f + i'_{kd})$$

$$i_{ds} = \frac{1}{L_{ls}} (\lambda_{ds} - \lambda_{md})$$

$$i'_f = \frac{1}{L'_{lf}} (\lambda'_f - \lambda_{md})$$

$$i'_{kd} = \frac{1}{L'_{lkd}} (\lambda'_{kd} - \lambda_{md})$$



$$\lambda_{md} = L_{MD} \left(\frac{\lambda_{ds}}{L_{ls}} + \frac{\lambda'_f}{L'_{lf}} + \frac{\lambda'_{kd}}{L'_{lkd}} \right)$$

where

$$\frac{1}{L_{MD}} = \frac{1}{L_{ls}} + \frac{1}{L'_{lf}} + \frac{1}{L'_{lkd}} + \frac{1}{L_{md}}$$



Wound Rotor Synchronous Machines

Currents in terms of flux linkages

$$\lambda_{mq} = L_{MQ} \left(\frac{\lambda_{qs}}{L_{ls}} + \frac{\lambda'_g}{L'_{l'g}} + \frac{\lambda'_{kq}}{L'_{lkq}} \right)$$

- Substituting the above expressions in the q -axis winding currents

$$i_{qs} = \frac{1}{L_{ls}} (\lambda_{qs} - \lambda_{mq})$$

$$i'_g = \frac{1}{L'_{l'g}} (\lambda'_g - \lambda_{mq})$$

$$i'_{kq} = \frac{1}{L'_{lkq}} (\lambda'_{kq} - \lambda_{mq})$$

yields

$$\begin{bmatrix} i_{qs} \\ i'_g \\ i'_{kq} \end{bmatrix} = \begin{bmatrix} \left(1 - \frac{L_{MQ}}{L_{ls}}\right) \frac{1}{L_{ls}} & -\frac{L_{MQ}}{L_{ls} L'_{l'g}} & -\frac{L_{MQ}}{L_{ls} L'_{lkq}} \\ -\frac{L_{MQ}}{L_{ls} L'_{l'g}} & \left(1 - \frac{L_{MQ}}{L'_{l'g}}\right) \frac{1}{L'_{l'g}} & -\frac{L_{MQ}}{L'_{l'g} L'_{lkq}} \\ -\frac{L_{MQ}}{L_{ls} L'_{lkq}} & -\frac{L_{MQ}}{L'_{l'g} L'_{lkq}} & \left(1 - \frac{L_{MQ}}{L'_{lkq}}\right) \frac{1}{L'_{lkq}} \end{bmatrix} \begin{bmatrix} \lambda_{qs} \\ \lambda'_g \\ \lambda'_{kq} \end{bmatrix}$$



Wound Rotor Synchronous Machines

Currents in terms of flux linkages

$$\lambda_{md} = L_{MD} \left(\frac{\lambda_{ds}}{L_{ls}} + \frac{\lambda'_f}{L'_{lf}} + \frac{\lambda'_{kd}}{L'_{lkd}} \right)$$

- Substituting the above expressions in the d -axis winding currents

$$i_{ds} = \frac{1}{L_{ls}} (\lambda_{ds} - \lambda_{md}) \quad i'_f = \frac{1}{L'_{lf}} (\lambda'_f - \lambda_{md}) \quad i'_{kd} = \frac{1}{L'_{lkd}} (\lambda'_{kd} - \lambda_{md})$$


yields

$$\begin{bmatrix} i_{ds} \\ i'_f \\ i'_{kd} \end{bmatrix} = \begin{bmatrix} \left(1 - \frac{L_{MD}}{L_{ls}}\right) \frac{1}{L_{ls}} & -\frac{L_{MD}}{L_{ls} L'_{lf}} & -\frac{L_{MD}}{L_{ls} L'_{lkd}} \\ -\frac{L_{MD}}{L_{ls} L'_{lf}} & \left(1 - \frac{L_{MD}}{L'_{lf}}\right) \frac{1}{L'_{lf}} & -\frac{L_{MD}}{L'_{lf} L'_{lkd}} \\ -\frac{L_{MD}}{L_{ls} L'_{lkd}} & -\frac{L_{MD}}{L'_{lf} L'_{lkd}} & \left(1 - \frac{L_{MD}}{L'_{lkd}}\right) \frac{1}{L'_{lkd}} \end{bmatrix} \begin{bmatrix} \lambda_{ds} \\ \lambda'_f \\ \lambda'_{kd} \end{bmatrix}$$



Simulation of Wound Rotor Synchronous Machines

- The winding equations of the derived model is implemented in a simulation that uses **voltages as inputs** and **currents as outputs**.






Simulation of Wound Rotor Synchronous Machines

Sub-systems: Transformation of stator voltages from *abc* system to *qd0* RF fixed to the rotor

Stator voltages

$$\begin{bmatrix} \mathbf{f}_{qd0} \end{bmatrix} = \begin{bmatrix} \mathbf{T}_{qd0} \end{bmatrix} \begin{bmatrix} \mathbf{f}_{abc} \end{bmatrix}$$




- It can be done in **two steps** (1: *abc* system to stationary *qd0* RF; 2: stationary *qd0* RF to rotor *qd0* RF) or in **single step**.



Simulation of Wound Rotor Synchronous Machines

Sub-systems: Voltage & flux linkage equations




The stator and rotor equations are coupled.



Simulation of Wound Rotor Synchronous Machines

Sub-systems: Torque equation



$$T_{em} = \frac{3}{2} \frac{P}{2} (\lambda_{ds} i_{qs} - \lambda_{qs} i_{ds})$$

or

$$T_{em} = \frac{3}{2} \frac{P}{2\omega_b} (\psi_{ds} i_{qs} - \psi_{qs} i_{ds})$$

where


$$\psi_{ds} = \omega_b \lambda_{ds}$$

$$\psi_{qs} = \omega_b \lambda_{qs}$$



Simulation of Wound Rotor Synchronous Machines

Sub-systems: Mechanical equation



Motoring Mode

$$T_{em} - T_{mech} - T_{damp} = J \frac{d\omega_{rm}}{dt}$$

Generating Mode

$$T_{em} + T_{mech} - T_{damp} = J \frac{d\omega_{rm}}{dt}$$




Simulation of Wound Rotor Synchronous Machines

Sub-systems: Transformation of stator current from rotor $qd0$ RF to abc system

Stator Currents

$$[\mathbf{f}_{abc}] = [\mathbf{T}_{qd0}]^{-1} [\mathbf{f}_{qd0}]$$



- It can be done in **two steps** (1: rotor $qd0$ RF to stationary $qd0$ RF; 2: stationary $qd0$ RF to abc system) or in **single step**.



Simulation of Wound Rotor Synchronous Machines

Transformation (Stator voltage)

- Transformation of the **stator voltages** from stator *abc* system to the **rotor** *qd0* RF.

$$\mathbf{T}_{qd0} = \frac{2}{3} \begin{bmatrix} \cos \theta_r & \cos \left(\theta_r - \frac{2\pi}{3} \right) & \cos \left(\theta_r + \frac{2\pi}{3} \right) \\ \sin \theta_r & \sin \left(\theta_r - \frac{2\pi}{3} \right) & \sin \left(\theta_r + \frac{2\pi}{3} \right) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix}$$

$$\mathbf{v}_{qd0} = \mathbf{T}_{qd0} \mathbf{v}_{abc}$$

$$v_{qs} = \frac{2}{3} \left\{ v_{as} \cos \theta_r + v_{bs} \cos \left(\theta_r - \frac{2\pi}{3} \right) + v_{cs} \cos \left(\theta_r - \frac{4\pi}{3} \right) \right\}$$

$$v_{ds} = \frac{2}{3} \left\{ v_{as} \sin \theta_r + v_{bs} \sin \left(\theta_r - \frac{2\pi}{3} \right) + v_{cs} \sin \left(\theta_r - \frac{4\pi}{3} \right) \right\}$$

$$v_{0s} = \frac{1}{3} (v_{as} + v_{bs} + v_{cs})$$



Simulation of Wound Rotor Synchronous Machines

Flux linkage and voltage equations

- The **reactance** is used instead of the **inductance**

$$x_y = \omega_b L_y \quad \longrightarrow \quad \psi_y = \omega_b \lambda_y$$

1. *d*-axis stator equations

$$v_{ds} = r_s i_{ds} + \frac{1}{\omega_b} \frac{d\psi_{ds}}{dt} - \frac{\omega_r}{\omega_b} \psi_{qs}$$
$$\psi_{ds} = x_{ls} i_{ds} + \psi_{md} \quad \longrightarrow \quad i_{ds} = \frac{1}{x_{ls}} (\psi_{ds} - \psi_{md})$$

1

$$\longrightarrow \quad \psi_{ds} = \omega_b \int \left\{ v_{ds} + \frac{\omega_r}{\omega_b} \psi_{qs} + \frac{r_s}{x_{ls}} (\psi_{md} - \psi_{ds}) \right\} dt$$

2

where $\psi_{md} = x_{md} (i_{ds} + i'_f + i'_{kd})$



Simulation of Wound Rotor Synchronous Machines

Flux linkage and voltage equations

2. q -axis stator equations

$$v_{qs} = r_s i_{qs} + \frac{1}{\omega_b} \frac{d\psi_{qs}}{dt} + \frac{\omega_r}{\omega_b} \psi_{ds}$$

$$\psi_{qs} = x_{ls} i_{qs} + \psi_{mq}$$



$$i_{qs} = \frac{1}{x_{ls}} (\psi_{qs} - \psi_{mq})$$

3



$$\psi_{qs} = \omega_b \int \left\{ v_{qs} - \frac{\omega_r}{\omega_b} \psi_{ds} + \frac{r_s}{x_{ls}} (\psi_{mq} - \psi_{qs}) \right\} dt$$

4

where

$$\psi_{mq} = x_{mq} (i_{qs} + i'_{kq})$$

3. Zero-component stator equations

$$v_{0s} = r_s i_{0s} + \frac{1}{\omega_b} \frac{d\psi_{0s}}{dt}$$

$$\psi_{0s} = x_{ls} i_{0s}$$



$$\psi_{0s} = \omega_b \int \left\{ v_{0s} - \frac{r_s}{x_{ls}} \psi_{0s} \right\} dt$$

5



Simulation of Wound Rotor Synchronous Machines

Flux linkage and voltage equations

4. d -axis rotor field winding equations

$$v'_f = r'_f i'_f + \frac{1}{\omega_b} d\psi'_f / dt$$

$$\psi'_f = x'_{lf} i'_f + \psi_{md} \quad \rightarrow \quad i'_f = \frac{1}{x'_{lf}} (\psi'_f - \psi_{md}) \quad 6$$

$$\rightarrow \quad \psi'_f = \omega_b \int \left\{ v'_f + \frac{r'_f}{x'_{lf}} (\psi_{md} - \psi'_f) \right\} dt \quad 7$$

5. d -axis rotor damper equations

$$0 = r'_{kd} i'_{kd} + \frac{1}{\omega_b} d\psi'_{kd} / dt$$

$$\psi'_{kd} = x'_{lkd} i'_{kd} + \psi_{md} \quad \rightarrow \quad i'_{kd} = \frac{1}{x'_{lkd}} (\psi'_{kd} - \psi_{md}) \quad 8$$

$$\rightarrow \quad \psi'_{kd} = \frac{\omega_b r'_{kd}}{x'_{lkd}} \int \left\{ (\psi_{md} - \psi'_{kd}) \right\} dt \quad 9$$



Simulation of Wound Rotor Synchronous Machines

Flux linkage and voltage equations

6. q -axis rotor damper equations

$$0 = r'_{kq} i'_{kq} + \frac{1}{\omega_b} d\psi'_{kq} / dt$$

$$\psi'_{kq} = x'_{lkq} i'_{kq} + \psi_{mq}$$



$$i'_{kq} = \frac{1}{x'_{lkq}} (\psi'_{kq} - \psi_{mq})$$

10



$$\psi'_{kq} = \frac{\omega_b r'_{kq}}{x'_{lkq}} \int \{(\psi_{mq} - \psi'_{kq})\} dt$$

11



Simulation of Wound Rotor Synchronous Machines

Flux linkage and voltage equations

- As before, to handle the **cut-set of inductors**, the following expressions are used:

$$\psi_{md} = x_{MD} \left(\frac{\psi_{ds}}{x_{ls}} + \frac{\psi'_f}{x'_{lf}} + \frac{\psi'_{kd}}{x'_{lkd}} \right) \quad \mathbf{12}$$

$$\frac{1}{x_{MD}} = \frac{1}{x_{ls}} + \frac{1}{x'_{lf}} + \frac{1}{x'_{lkd}} + \frac{1}{x_{md}}$$


$$\psi_{mq} = x_{MQ} \left(\frac{\psi_{qs}}{x_{ls}} + \frac{\psi'_{kq}}{x'_{lkq}} \right) \quad \mathbf{13}$$

$$\frac{1}{x_{MQ}} = \frac{1}{x_{ls}} + \frac{1}{x'_{lkq}} + \frac{1}{x_{mq}}$$



Simulation of Wound Rotor Synchronous Machines

Flux linkage and voltage equations: q -axis block diagram





Simulation of Wound Rotor Synchronous Machines

2-Step Transformation of the Stator Currents

- Transformation from the **rotor $qd0$** RF to the **stator $qd0$** RF:

$$\left\{ \begin{array}{l} i_{qs}^s = i_{qs} \cos \theta_r + i_{ds} \sin \theta_r \\ i_{ds}^s = -i_{qs} \sin \theta_r + i_{ds} \cos \theta_r \end{array} \right.$$

- Transformation from the **stator $qd0$** RF to **abc system**:

$$\left\{ \begin{array}{l} i_{as} = i_{qs}^s + i_{0s} \\ i_{bs} = -\frac{1}{2} i_{qs}^s - \frac{1}{\sqrt{3}} i_{ds}^s + i_{0s} \\ i_{cs} = -\frac{1}{2} i_{qs}^s + \frac{1}{\sqrt{3}} i_{ds}^s + i_{0s} \end{array} \right.$$



Per-Unit System

Base quantities

- The base quantities with **peak** rather than rms value of a P -pole, three-phase synchronous machine with **rated line-to-line rms voltage**, V_{rated} , and **rated volt-ampere**, S_{rated} , are as follows:

Base Voltage

$$V_b = \sqrt{\frac{2}{3}} V_{rated}$$

Base Volt-ampere

$$S_b = S_{rated}$$

Base Peak Current

$$I_b = 2S_b / (3V_b)$$

Base Impedance

$$Z_b = V_b / I_b$$

Base Torque

$$T_b = S_b / \omega_{bm}$$

where

$$\omega_{bm} = 2\omega_b / P$$



Per-Unit System

Torque Equation

$$T_{em} = \frac{3}{2} \frac{P}{2\omega_b} (\psi_{ds} i_{qs} - \psi_{qs} i_{ds})$$

$$T_b = \frac{S_b}{\omega_{bm}} \xrightarrow{\omega_{bm} = 2\omega_b / P} T_b = \frac{S_b}{\frac{2}{P} \omega_b} \xrightarrow{I_b = 2S_b / (3V_b)} T_b = \frac{3}{2} \frac{P}{2} \frac{V_b I_b}{\omega_b}$$

$$\frac{T_{em}}{T_b} = \frac{\frac{3}{2} \frac{P}{2\omega_b} (\psi_{ds} i_{qs} - \psi_{qs} i_{ds})}{\frac{3}{2} \frac{P}{2\omega_b} V_b I_b} \Rightarrow T_{em}(pu) = \psi_{ds}(pu) i_{qs}(pu) - \psi_{qs}(pu) i_{ds}(pu)$$

where

$$\psi_{ds}(pu) = \frac{\psi_{ds}}{V_b}$$

$$\psi_{qs}(pu) = \frac{\psi_{qs}}{V_b}$$

$$i_{qs}(pu) = \frac{i_{qs}}{I_b}$$

$$i_{ds}(pu) = \frac{i_{ds}}{I_b}$$



Per-Unit System

Mechanical Equation

$$J \frac{d\omega_{rm}}{dt} = T_{em} + T_{mech} - T_{damp}$$

$$\omega_{rm} = 2\omega_r / P$$

$$\frac{2J\omega_b}{P} \frac{d(\omega_r / \omega_b)}{dt} = T_{em} + T_{mech} - T_{damp} *$$



$$T_b = S_b / \omega_{bm}$$

$$\omega_{bm} = 2\omega_b / P$$

$$2H \frac{d(\omega_r / \omega_b)}{dt} = T_{em}(pu) + T_{mech}(pu) - T_{damp}(pu)$$

where $H = J\omega_{bm}^2 / (2S_b)$ is the inertia constant.



Machine Parameters

The following machine parameters are required for the simulation

- x_{ls} stator or armature winding **leakage** reactance
- x'_{lf} d -axis field winding **leakage** reactance referred to stator
- x'_{lkd} d -axis damper winding **leakage** reactance referred to stator
- x'_{lkq} q -axis damper winding **leakage** reactance referred to stator
- x_{md} d -axis **magnetizing** reactance
- x_{mq} q -axis **magnetizing** reactance
- r_s stator or armature winding **resistance**
- r'_f d -axis field winding **resistance** referred to stator
- r'_{kd} d -axis damper winding **resistance** referred to stator
- r'_{kq} q -axis damper winding **resistance** referred to stator



Machine Parameters

Other parameters/quantities required for simulation are:

- J rotor **moment of inertia**
- P **number of poles**
- ω_b rotor **base speed**
- V_{rated} rated line-to-line rms **voltage of stator**
- S_{rated} rated **volt-ampere**
- T_{mech} mechanical **load torque** profile

Machine Parameters



- The machine data from manufacturers are usually in the form of
 - **reactances**,
 - **time constants**, and
 - **resistances**.
- Most of them are derived from **measurements** taken from the **stator** windings.
- Rotor winding parameters can be obtained from stator measurements, because the effective **time constants** of various rotor currents are significantly **different**.
- A common approach is the **short-circuit oscillogram** of the stator currents, when a 3-phase short-circuit is applied to the machine whose stator is initially open-circuit and its field held constant.

Machine Parameters



- The **short-circuit current** consists of:
 - **DC offset**
 - **Sub-transient** period
 - **Transient** period
 - **Steady-state** period
- During the **sub-transient** period the current decay is very **rapid**, due to the changes in the currents of **damper** windings.
- The current decay is **slower** during the **transient** period and is attributed to changes in the currents of the **field** windings.




Machine Parameters

The flux path of d -axis during different periods


Steady-state

Transient


Sub-transient



(a) L_d



(b) L'_d




(c) L''_d



Machine Parameters


The flux path of q -axis during different periods

Steady-state




(a) L_q

Transient



(b) L'_q

Sub-transient




(c) L''_q




Machine Parameters

Synchronous Inductances



$$L_q = L_{ls} + L_{mq}$$


$$L_d = L_{ls} + L_{md}$$





Machine Parameters

Transient Inductances




$$L'_q = L_{ls} + L_{mq} \parallel L'_{lg}$$

$$L'_q = L_{ls} + \frac{L_{mq} L'_{lg}}{L_{mq} + L'_{lg}}$$

$$L'_d = L_{ls} + L_{md} \parallel L'_{lf}$$

$$L'_d = L_{ls} + \frac{L_{md} L'_{lf}}{L_{md} + L'_{lf}}$$






Machine Parameters

Transient Inductances

- During the transient period $\Delta\lambda_f = 0$ and $\Delta i'_{kd} = 0$

$$\Delta\lambda_f = L_{md}\Delta i_d + L'_{ff}\Delta i'_f = 0$$

$$\Delta\lambda_d = L_d\Delta i_d + L_{md}\Delta i'_f$$



$$\Delta\lambda_d = \left(L_d - \frac{L_{md}^2}{L'_{ff}} \right) \Delta i_d$$

$$L'_d = \frac{\Delta\lambda_d}{\Delta i_d} = L_d - \frac{L_{md}^2}{L'_{ff}}$$

which is the same as

$$L'_d = L_{ls} + \frac{L_{md}L'_{lf}}{L_{md} + L'_{lf}}$$


- Similarly for the q-axis

$$L'_q = \frac{\Delta\lambda_q}{\Delta i_q} = L_q - \frac{L_{mq}^2}{L'_{gg}}$$




Machine Parameters

Sub-transient Inductances



$$L''_q = L_{ls} + L_{mq} \parallel L'_{lg} \parallel L'_{lkq}$$

$$L''_d = L_{ls} + L_{md} \parallel L'_{lf} \parallel L'_{lkd}$$





Machine Parameters

Sub-transient Inductances

- During the sub-transient period in d-axis $\Delta\lambda'_f = 0$ and $\Delta\lambda'_{kd} = 0$

$$\Delta\lambda'_f = L_{md}\Delta i_d + L'_{ff}\Delta i'_f + L_{md}\Delta i'_{kd} = 0$$

$$\Delta\lambda'_{kd} = L_{md}\Delta i_d + L_{md}\Delta i'_f + L_{kdkd}\Delta i'_{kd} = 0$$

Writing $\Delta i'_f$ and $\Delta i'_{kd}$ in terms of Δi_d and substituting in

$$\Delta\lambda_d = L_d\Delta i_d + L_{md}\Delta i'_f + L_{md}\Delta i'_{kd}$$

yields

$$L''_d = \frac{\Delta\lambda_d}{\Delta i_d} = L_d - \frac{L_{md}^2(L'_{lkd} + L'_{lf})}{L'_{ff}L'_{kdkd} - L_{md}^2}$$

which is the same as

$$L''_d = L_{ls} + \frac{L_{md}L'_{lkd}L'_{lf}}{L'_{lkd}L'_{lf} + L_{md}(L'_{lkd} + L'_{lf})}$$



Machine Parameters

Sub-transient Inductances

- During the sub-transient period in q-axis $\Delta\lambda'_g = 0$ and $\Delta\lambda'_{kq} = 0$

$$\Delta\lambda'_g = L_{mq}\Delta i_q + L'_{gg}\Delta i'_g + L_{mq}\Delta i'_{kq} = 0$$

$$\Delta\lambda'_{kq} = L_{mq}\Delta i_q + L_{mq}\Delta i'_g + L_{kqkq}\Delta i'_{kq} = 0$$

Writing $\Delta i'_g$ and $\Delta i'_{kq}$ in terms of Δi_q and substituting in

$$\Delta\lambda_q = L_q\Delta i_q + L_{mq}\Delta i'_g + L_{mq}\Delta i'_{kq}$$

yields

$$L''_q = \frac{\Delta\lambda_q}{\Delta i_q} = L_q - \frac{L_{mq}^2(L'_{lkq} + L'_{lg})}{L'_{gg}L'_{kqkq} - L_{mq}^2}$$

which is the same as

$$L''_q = L_{ls} + \frac{L_{mq}L'_{lkq}L'_{lg}}{L'_{lkq}L'_{lg} + L_{mq}(L'_{lkq} + L'_{lg})}$$




Machine Parameters

Open-circuit transient time constant

- When the stator is open-circuited and the effects of higher winding resistance, damper windings, are neglected, the **open-circuit time constants** of the **field** winding are defined as:

$$T'_{do} = \frac{L'_{ff}}{r'_f} = \frac{L'_{lf} + L_{md}}{r'_f}$$

$$T'_{qo} = \frac{L'_{gg}}{r'_g} = \frac{L'_{lg} + L_{mq}}{r'_g}$$






Machine Parameters

Short-circuit transient time constant

- When the stator is short-circuited and the effects of higher winding resistance, damper windings, are neglected, the **short-circuit time constants** of the **field** winding are defined as:

$$T'_d = \frac{L'_{lf} + L_{md} \parallel L_{ls}}{r'_f}$$

$$T'_q = \frac{L'_{lg} + L_{mq} \parallel L_{ls}}{r'_g}$$





Machine Parameters

Transient time constant

- The ratio of the time constants of the field winding with short-circuited stator windings to that with open-circuit stator winding is equal to the ratio of the apparent inductance seen by the stator current with field short-circuited to that with field open-circuited:

$$\frac{T'_d}{T'_{do}} = \frac{L'_d}{L_d}$$

where

$$L_d = L_{ls} + L_{md} \quad \text{and}$$

$$L'_d = L_{ls} + \frac{L_{md} L'_{lf}}{L_{md} + L'_{lf}}$$

$$\frac{T'_q}{T'_{qo}} = \frac{L'_q}{L_q}$$

where

$$L_q = L_{ls} + L_{mq} \quad \text{and}$$

$$L'_q = L_{ls} + \frac{L_{mq} L'_{lg}}{L_{mq} + L'_{lg}}$$

Why?





Machine Parameters

Open-circuit sub-transient time constant

- The open-circuit sub-transient time constants are the time constants of the **damper winding current** when the **stator is open-circuited** and the **field winding is short-circuited**.

$$T''_{do} = \frac{L'_{lkd} + L_{md} \parallel L'_{lf}}{r'_{kd}}$$

$$T''_{qo} = \frac{L'_{lkq} + L_{mq} \parallel L'_{lg}}{r'_{kq}}$$






Machine Parameters


Short-circuit sub-transient time constant

- The short-circuit sub-transient time constants are the time constants of the **damper winding current** when the **stator** and the **field** windings are **both short-circuited**.

$$T_d'' = \frac{L'_{lkd} + L_{md} \parallel L'_{lf} \parallel L_{ls}}{r'_{kd}}$$



$$T_q'' = \frac{L'_{lkq} + L_{mq} \parallel L'_{lg} \parallel L_{ls}}{r'_{kq}}$$





Machine Parameters

Calculations of Machine Parameters

- Assume the following parameters are given by the manufacturers:

$$x_d, x_q, x'_d, x'_q, x''_d, x''_q, x_{ls}, r_s, T'_{do}, T'_d, T''_{do}, T''_{qo}, T''_d, T''_q$$

- Based on the above given parameters, the following parameters are calculated:

$$x_{md}, x_{mq}, x'_{lf}, x'_{lkd}, x'_{lkq}, r'_f, r'_{kd}, r'_{kq}.$$

- The armature leakage reactance is normally given; but if it is not given, the value of the zero-sequence reactance may be used instead:

$$x_{ls} = x_0$$



Machine Parameters

Calculations of Machine Parameters (x_{md} , x_{mq} , x'_{lf})


- The **direct and quadrature magnetizing reactances** are obtained:

$$x_{mq} = x_q - x_{ls}$$

$$x_{md} = x_d - x_{ls}$$

- The **field leakage reactance** is obtained using:

$$x'_d = x_{ls} + \frac{x_{md} x'_{lf}}{x_{md} + x'_{lf}}$$



$$x'_{lf} = \frac{x_{md} (x'_d - x_{ls})}{x_{md} - (x'_d - x_{ls})}$$

- If $x_{md} \gg x'_{lf}$:



$$x'_{lf} \approx x'_d - x_{ls}$$



Machine Parameters

Calculations of Machine Parameters (x'_{lkd})


- The **leakage reactance of the d-axis damper winding** is calculated using:

$$x''_d = x_{ls} + \frac{x_{md} x'_{lf} x'_{lkd}}{x_{md} x'_{lf} + x_{md} x'_{lkd} + x'_{lkd} x'_{lf}}$$



$$x'_{lkd} = \frac{(x''_d - x_{ls}) x_{md} x'_{lf}}{x_{md} x'_{lf} - (x''_d - x_{ls}) (x_{md} + x'_{lf})}$$

- If $x_{md} \gg x'_{lf}$



$$x'_{lkd} \approx \frac{(x''_d - x_{ls}) x'_{lf}}{x'_{lf} - (x''_d - x_{ls})}$$



Machine Parameters

Calculations of Machine Parameters (x'_{lkq})

- Having no g-winding in the q-axis ($x_{lg} \rightarrow \infty$), the **leakage reactance of the q-axis damper winding** is calculated using:

$$x''_q = x_{ls} + \frac{x_{mq} x'_{lkq}}{x_{mq} + x'_{lkq}} \quad \Rightarrow \quad x'_{lkq} = \frac{x_{mq} (x''_q - x_{ls})}{x_{mq} - (x''_q - x_{ls})}$$

- If $x_{mq} \gg x'_{lkq} \quad \Rightarrow \quad x'_{lkq} \approx x''_q - x_{ls}$

- The time constants are used to calculate the resistances of the rotor windings.




Machine Parameters


Calculations of Machine Parameters (r'_f)

- The **field resistance** is calculated from the **d-axis transient open-circuit time constant**:

$$T'_{do} = \frac{1}{\omega_b r'_f} (x'_{lf} + x_{md})$$



$$r'_f = \frac{1}{\omega_b T'_{do}} (x'_{lf} + x_{md})$$





Machine Parameters


Calculations of Machine Parameters (r'_{kd})

- The **d-axis damper resistance** is calculated from the **d-axis sub-transient open-circuit time constant**:


$$T''_{do} = \frac{1}{\omega_b r'_{kd}} \left(x'_{lkd} + \frac{x_{md} x'_{lf}}{x_{md} + x'_{lf}} \right)$$

or

$$T''_{do} = \frac{1}{\omega_b r'_{kd}} (x'_{lkd} + x'_d - x_{ls})$$



$$r'_{kd} = \frac{1}{\omega_b T''_{do}} (x'_{lkd} + x'_d - x_{ls})$$






Machine Parameters


Calculations of Machine Parameters (r'_{kq})

- The **q-axis damper resistance** is calculated from the **q-axis sub-transient open-circuit time constant**:

$$T''_{qo} = \frac{1}{\omega_b r'_{kq}} (x'_{lkq} + x_{mq})$$



$$r'_{kq} = \frac{1}{\omega_b T''_{qo}} (x'_{lkq} + x_{mq})$$





Machine Parameters

Calculations of Machine Parameters


- Alternatively, the short-circuit time constants can be used to calculate the rotor resistances:

$$r'_f = \frac{1}{\omega_b T'_d} \left(x'_{lf} + \frac{x_{md} x_{ls}}{x_{md} + x_{ls}} \right)$$

$$r'_{kd} = \frac{1}{\omega_b T''_d} \left(x'_{lkd} + \frac{x_{md} x_{ls} x'_{lf}}{x_{md} x_{ls} + x_{md} x'_{lf} + x_{ls} x'_{lf}} \right)$$


$$r'_{kq} = \frac{1}{\omega_b T''_q} \left(x'_{lkq} + \frac{x_{mq} x_{ls}}{x_{mq} + x_{ls}} \right)$$

Permanent Magnet Synchronous Machines



PM Synchronous Machines

- The DC excitation of the field winding in a synchronous machine can be provided by **permanent magnets**.
- So the **rotor copper losses** are **eliminated**.
- PMSMs can offer **simpler construction, lower weight and size**, reduced losses and thus higher efficiency.
- The disadvantages of PMSMs are the **higher prices** if rare-earth magnets are used.





PM Synchronous Machines

$qd0$ equations referred to the stator side

Stator

$$v_q = r_s i_q + d\lambda_q/dt + \omega_r \lambda_d$$

$$v_d = r_s i_d + d\lambda_d/dt - \omega_r \lambda_q$$

$$v_0 = r_s i_0 + d\lambda_0/dt$$

$$\lambda_q = L_q i_q + L_{mq} i'_{kq}$$

$$\lambda_d = L_d i_d + L_{md} i'_m + L_{md} i'_{kd}$$

$$\lambda_0 = L_{ls} i_0$$

Rotor

$$0 = r'_{kd} i'_{kd} + d\lambda'_{kd}/dt$$

$$0 = r'_{kq} i'_{kq} + d\lambda'_{kq}/dt$$

$$\lambda'_{kq} = L_{mq} i_q + L'_{kqkq} i'_{kq}$$

$$\lambda'_{kd} = L_{md} i_d + L_{md} i'_m + L'_{kdkd} i'_{kd}$$

where i'_m is the equivalent magnetizing current of the PMs.



PM Synchronous Machines

q -axis equivalent circuit

Stator


$$v_q = r_s i_q + d\lambda_q/dt + \omega \lambda_d$$

$$\lambda_q = L_{ls} i_q + L_{mq} (i_q + i'_{kq})$$

Rotor

$$0 = r'_{kq} i'_{kq} + d\lambda'_{kq}/dt$$

$$\lambda'_{kq} = L'_{lkq} i'_{kq} + L_{mq} (i_q + i'_{kq})$$





PM Synchronous Machines

d-axis equivalent circuit

Stator


Rotor

$$v_d = r_s i_d + d\lambda_d / dt - \omega \lambda_q$$

$$0 = r'_{kd} i'_{kd} + d\lambda'_{kd} / dt$$

$$\lambda_d = L_{ls} i_d + L_{md} (i_d + i'_m + i'_{kd})$$

$$\lambda'_{kd} = L'_{lkd} i'_{kd} + L_{md} (i_d + i'_m + i'_{kd})$$



The PM reluctance can be represented by a virtual inductance denoted by L_{rc} , that is associated with its recoil slope

$$L_{md} + L_{rc} \rightarrow L_{md}$$




PM Synchronous Machines

Zero-component equivalent circuit

Stator

$$v_0 = r_s i_0 + d\lambda_0 / dt$$

$$\lambda_0 = L_{ls} i_0$$





PM Synchronous Machines

Torque Equation

- Similar to wound rotor synchronous machine, the electromagnetic torque of PMSMs is obtained by

$$T_{em} = \frac{3}{2} \frac{P}{2} (\lambda_d i_q - \lambda_q i_d)$$

where P is the number of poles.

- It can be rewritten as:

$$T_{em} = \underbrace{\frac{3}{2} \frac{P}{2} (L_d - L_q) i_d i_q}_{\text{Reluctance torque}} + \underbrace{\frac{3}{2} \frac{P}{2} (L_{md} i'_{kd} i_q - L_{mq} i'_{kq} i_d)}_{\text{Induction torque}} + \underbrace{\frac{3}{2} \frac{P}{2} L_{md} i'_m i_q}_{\text{Excitation torque}}$$

where

$$L_d = L_{ls} + L_{md}$$

and

$$L_q = L_{ls} + L_{mq}$$



PM Synchronous Machines

Mechanical Dynamic Equation

- Based on Newton's 2nd law for rotational movement, $\sum T = J \frac{d\omega_{rm}}{dt}$ the **mechanical dynamic equation** is obtained:

Motoring Mode

$$T_{em} - T_{mech} - T_{damp} = J \frac{d\omega_{rm}}{dt}$$

Generating Mode

$$T_{em} + T_{mech} - T_{damp} = J \frac{d\omega_{rm}}{dt}$$

where T_{mech} is the externally-applied mechanical torque, T_{damp} is the damping torque, J is the moment of inertia and ω_{rm} is the mechanical rotational velocity.